

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G8L3419U

Toyota Hiace

GDH2011007808

Rear Bumper.	700(SN)	
Rear Sensor.	200(SN)	
Taillamp	350	
Taillight	1800	3300
Taillight Lock	300	2475
Taillight Weatherstripe.	300	S.N: 1450
End Panel	550	
Stickers.	350(SN)	
Exhaust Tail Pipe.	200(SN)	
Labour	700	
Spay	200.	
Wing	300	1650
Sensor	50	total: 5575
Caner	50	L/S: 4450
Windsreen	120.	Rep's Range: 4510-4810
		06211.