

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22002098/Eqy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 16/03/2022 SINGAPORE 068811 ATTN: LOH CYNTHIA Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 5684H Veh. Inspected SJA 5751J Policy No. VFX/P2413997 Coverage (\$) 0.00 Claim No. S2M03UZ7 Excess (\$) 0.00 **Assign Date LOH CYNTHIA** 07/03/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA WISH Make & Model 1794 C.C HIDDEN 2007 Engine No. Year of Reg. ZNE100375450 SILVER Chassis No. Colour Odometer 253099 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 BRIDGESTONE 5 mm L/H Front Tyre 195/65 R15 BRIDGESTONE 5 mm 195/65 R15 BRIDGESTONE R/H Rear Tyre 5 mm BRIDGESTONE L/H Rear Tyre 195/65 R15 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information** 04/03/2022 08/03/2022 (12:03 PM) Inspect Date / Time Accident Date MASTER CAR SPRAY SERVICE Survey held at 36 TOH GUAN ROAD EAST #01-48 ENTERPRISE HUB SINGAPORE 608580 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000

Report Ref No. CS3/ASM22002098/Eqy3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

9 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser