

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909 Code: UOI2 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SLB 1678K Veh. Inspected SMG 6982K Policy No. Coverage (\$) Claim No. M12D17932203 Excess (\$) Assign From WONG JOSEPHINE Ref: CS/UOI2200209 Date: 12/04/2022 12/04/2022 0.002 Code: UOI2 1. Policy Particulars: - THIRD PARTY CLAIM Veh. Inspected SMG 6982K O.000 Assign From WONG JOSEPHINE Assign Date O7/03/2022	99/Ety3e2	
#02-01 UOI BUILDINGSINGAPORE 068909 Code: UOI2 1.		
Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SLB 1678K Veh. Inspected SMG 6982K Policy No. Coverage (\$) 0.00 Claim No. M12D17932203 Excess (\$) 0.00		
Insured Veh. SLB 1678K Veh. Inspected SMG 6982K		
Policy No. Coverage (\$) 0.00 Claim No. M12D17932203 Excess (\$) 0.00	1. Policy Particulars :- THIRD PARTY CLAIM	
Claim No. M12D17932203 Excess (\$) 0.00		
Assign From WONG JOSEPHINE Assign Date 07/03/2022		
1		
2. Vehicle Particulars & Condition		
Make & Model VOLKSWAGEN TIGUAN c.c 1395		
Engine No. HIDDEN Year of Reg. 2018		
Chassis No. WVGZZZ5NZJW972930 Colour WHITE		
Odometer 48521 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm		
L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm		
R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm		
L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 04/03/2022 Inspection Date 09/03/2022		
Survey held at VOLKSWAGEN CENTRE SINGAPORE		
247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days		