

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002101/APA3Q2**Date:** 04/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900003785
Claimant Vehicle No :	SLK2942T	Insured Vehicle No :	SMH1853C
Date of Loss:	03/03/2022	Nature of Claim:	TP
		Claim No:	1961150355SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2942T	Engine No:	L15B3538105
Make & Model:	HONDA SHUTTLE, 1.5 G (A)	Chassis No:	GK81006902
Reg. Date:	12/01/2017 (Man. Year: 2016)	Odometer:	129873 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,371.68	6,580.80	11,790.88	64.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	2,200.00	3,160.00	58.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,731.68	8,780.80	14,950.88	63.00
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	23,731.68	7,000.00	16,731.68	70.50
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,396.45		

INSPECTION

Date of Assignment:	04/03/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	04/03/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,600.00 FL	*985.00 FL
2	1		*REAR BUMPER EXHAUST COVER GARNISH	Not Necessary	57.00 FL	*- FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	98.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR GARNISH	Not Necessary	136.00 FL	*- FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	19.00 FL	*- FL
6	1		*REAR BUMPER TOWING BRACKET	Not Necessary	294.00 FL	*- FL
7	2		*REAR BUMPER SIDE INNER BRACKET	Not Necessary	78.00 FL	*- FL
8	2		*REAR BUMPER SPONGE	Cracked	94.00 FL	*94.00 FL
9	2		*REAR BUMPER SIDE RETAINER	Necessary	64.00 FL	*64.00 FL
10	1		*TAIL GATE	Distorted	1,900.00 FL	*1,192.00 FL
11	1		*TAIL GATE OUTER GARNISH C/W MOULDING (CHROME)	Not Necessary	695.00 FL	*- FL
12	2		*TAIL GATE NUMBER PLATE LAMP	Not Necessary	76.00 FL	*- FL
13	1		*TAIL GATE LOGO	Not Necessary	45.00 FL	*- FL
14	1		*TAIL GATE EMBLEM SHUTTLE	Necessary	70.00 FL	*70.00 FL
15	2		*TAIL GATE LAMP	Cut	790.00 FL	*790.00 FL
16	2		*TAIL GATE DAMPER	Not Necessary	250.00 FL	*- FL
17	2		*TAIL GATE HINGE	Not Necessary	100.00 FL	*- FL
18	1		*TAIL GATE INNER HOLDER	Not Necessary	40.00 FL	*- FL
19	2		*TAIL GATE STOPPER	Not Necessary	50.00 FL	*- FL
20	1		*TAIL GATE INNER LOCK	Damaged	190.00 FL	*190.00 FL
21	1		*TAIL GATE LOCK CATCH	Not Necessary	24.00 FL	*- FL
22	1		*TAIL GATE WEATHERSTRIP	Cut	190.00 FL	*190.00 FL
23	1		*TAIL GATE DETECTOR	Not Necessary	296.00 FL	*- FL
24	1		*TAIL GATE DETECTOR WIRE HARNESS	Not Necessary	586.00 FL	*- FL
25	1		*TAIL GATE INNER TRIM	Cracked	320.00 FL	*320.00 FL
26	1		*TAIL GATE REVERSE CAMERA	Not Necessary	1,150.60 FL	*- FL
27	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	160.00 FL	*160.00 FL
28	1		*REAR BUZZER	Not Necessary	170.00 FL	*- FL
29	2		*TAIL LAMP	Cut	1,040.00 FL	*1,040.00 FL
30	2		*TAIL LAMP LOWER PANEL (OUTER)	Not Necessary	544.00 FL	*- FL
31	2		*TAIL LAMP INNER PANEL (LOWER)	Not Necessary	398.00 FL	*- FL
32	2		*REAR FENDER COWLING	Not Necessary	294.00 FL	*- FL
33	1		*REAR FENDER INNER TRIM	N/S Cracked	1,100.00 FL	*450.00 FL
34	2		*REAR FENDER AIR VENT	Not Necessary	116.00 FL	*- FL
35	1		*REAR END PANEL	Dented	920.00 FL	*681.00 FL
36	1		*REAR END PANEL TOP GARNISH	Cracked	155.00 FL	*155.00 FL
37	1		*REAR FLOOR PANEL	Repair	1,600.00 FL	*- FL
38	1		*REAR FLOOR PANEL TOP OUTER COVER BOARD	Deformed	585.00 FL	*585.00 FL
39	2		*REAR FLOOR PANEL TOP SIDE COVER BOARD	Not Necessary	300.00 FL	*- FL
40	1		*REAR FLOOR PANEL TOP INNER COVER BOARD	Not Necessary	340.00 FL	*- FL
41	1		*REAR STORAGE BOX (SPONGE)	Not Necessary	250.00 FL	*- FL
42	1		*REAR STORAGE BOX (PLASTIC)	Cracked	495.00 FL	*495.00 FL
43	1		*REAR TOOLS SPONGE TRAY	Not Necessary	185.00 FL	*- FL
44	1		*REAR JACK COVER GARNISH	Deformed	190.00 FL	*190.00 FL
45	1		*REAR JACK	Not Necessary	145.00 FL	*- FL
46	1		*REAR CHASSIS FRAME LH	Repair	550.00 FL	*- FL
47	1		*REAR EXHAUST PIPE	Not Necessary	745.00 FL	*- FL
48	1		*REAR EXHAUST INSULATOR	Not Necessary	195.00 FL	*- FL
49	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
50	4		*REAR EXHAUST MOUNTING	Not Necessary	340.00 FL	*- FL
51	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
52	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
53	1		*SET REAR BUMPER EXHAUST COVER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
54	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
55	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

1/4/23, 11:21 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
57	1		*TAIL GATE WINDSCREEN INNER SOLAR FILM	Not Necessary	550.00 FS	*- FS
58	1		*SET TAIL LAMP CLIP	Necessary	60.00 FS	*20.00 FS
59	2		*TAIL LAMP LOWER PANEL (OUTER)SEALANT	Not Necessary	160.00 FS	*- FS
60	2		*TAIL LAMP INNER PANEL (LOWER)SEALANT	Not Necessary	160.00 FS	*- FS
61	1		*SET REAR FENDER INNER COWLING	Not Necessary	80.00 FS	*- FS
62	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
63	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
64	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
65	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
66	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					22,389.60	8,111.00
- List Item Discount on L Items 20.00/20.00% (S\$)					4,017.92	1,530.20
Total Parts (S\$)					18,371.68	6,580.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,400.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,000.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
5	REAR CHASSIS ALIGNMENT	New	250.00	0.00
6	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
7	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			5,360.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >