3/16/22, 1:41 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI22002109/KTY3N2

16/03/2022 Date:

**REFERENCE** 

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle SMY621Y** No:

Insured Vehicle No: SLL2466X

Date of Loss: 20/02/2022 Nature of Claim: ΤP Claim No: CDMPG22000411

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SMY621Y** 

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G81449

Reg. Date: 10/02/2021 (Man. Year: 2020) Chassis No: JTDKB3FU203091513

Colour: Odometer: 128932 km Metallic Silver

**Engine Capacity:** 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Sailun 6 mm Firenza 9 mm Front Right Side: Firenza 9 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,783.45	1,097.50	2,685.95	70.99
Miscellaneous Items		0.00	0.00	0.00	
Labour		7,390.00	480.00	6,910.00	93.50
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gross Tota	I (S\$)	11,173.45	1,577.50	9,595.95	85.88
+ GST 7.00/7.00%	% (S\$)	782.14	110.43	671.71	85.88
Nett Amoun	t (S\$)	11,955.59	1,687.93	10,267.66	85.88

**INSPECTION** 

Date of Assignment: 07/03/2022

Trans-cab Auto Services Pte Ltd Date Inspected: 08/03/2022 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### Reference

3/16/22, 1:41 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Mar 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY621Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*COVER,REAR BUMPER LOWER	Serviceable	22.00 FL	*-FL
4	1		*GUARD REAR BUMPER CENTER	Mtg Cracked	374.50 FL	*374.50 FL
5	1		*COVER,FLOOR UNDER NO 2 (RH)	Serviceable	241.90 FL	*-FL
6	1		*COVER,FLOOR UNDER NO 1 (LH)	Serviceable	175.10 FL	*- FL
7	1		*COVER,REAR FLOOR CTR	Cracked	229.90 FL	*229.90 FL
8	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	132.60 FL	*- FL
9	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	132.60 FL	*- FL
10	1		*COVER DECK TRIM,REAR	Serviceable	126.70 FL	*- FL
11	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	651.00 FL	*- FL
12	1		*SET PARKING AID	Shorted	700.00 FS	*220.00 FS
13	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
14	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
15	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*-FS
16	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
17	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*-FS
18	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
19	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	4,509.60	1,370.00
			- List Item Discount on L It	ems 25.00/25.00% (S\$)	726.15	272.50
				Total Parts (S\$)	3,783.45	1,097.50
				-		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	200.00
3	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
5	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	220.00
9	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
11	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATOR	New	380.00	0.00
	Gross Labou	r Cost (S\$)	7,390.00	480.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >