

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22002112/ETY3N2**Date:** 24/04/2022**REFERENCE**

Insured/Claimant: COMFORTDELGRO BUS PTE LTD Policy No: D20MFL0003256_01
Date of Loss: 06/03/2022 Nature of Claim: OD Claim No: MFL2022D0001114

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC9522X**
Make & Model: TOYOTA COASTER, 4.0 D (M) Engine No: N04CWA10393
Reg. Date: 18/12/2020 (Man. Year: 2019) Chassis No: JTGFD838606000129
Colour: White Odometer: 37366 km
Engine Capacity: 4009 cc
Market Value/New Car Price: S\$138,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R17.5 Rear Tyre Size: 215/70 R17.5
Front Left Side: DURATURN 4 mm Rear Left Side: DURATURN 4 mm
Front Right Side: DURATURN 4 mm Rear Right Side: DURATURN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,614.69	26,038.66	14,576.03	35.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,010.00	3,690.00	320.00	7.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,624.69	29,728.66	14,896.03	33.38
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	43,124.69	28,228.66	14,896.03	34.54
+ GST 7.00/7.00% (S\$)	3,018.73	1,976.01	1,042.72	34.54
Nett Amount (S\$)	46,143.42	30,204.67	15,938.75	34.54

INSPECTION

Date of Assignment: 07/03/2022
Date Inspected: 08/03/2022 Inspected At: Connect3 (HQ)
566 Woodlands Road
Singapore 728697
Estimated Period of Repair: 20.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Apr 2022)	
Parts:	N/A	TOYOTA COASTER 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC9522X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,471.50 F	*1,471.50 FL
2	1		*FRONT BUMPER RETAINER LH (UPPER & LOWER)	Missing	256.00 F	*256.00 FL
3	10		*FRONT BUMPER CLIPS	Necessary	25.00 F	*20.00 FL
4	1		*FRONT BUMPER CENTER GRILLE	Broken	450.00 F	*450.00 FL
5	1		*FRONT PANEL	Dented	3,545.80 F	*3,545.80 FL
6	1		*FRONT WINDSCREEN	Broken	2,988.60 F	*2,988.60 FL
7	1		*FRONT WINDSCREEN INNER SEAL	Necessary	423.40 F	*423.40 FL
8	1		*FRONT LH HEADLAMP UPPER COVER	Missing	280.00 F	*280.00 FL
9	1		*FRONT GRILLE COVER	Broken	350.00 F	*350.00 FL
10	1		*FRONT GRILLE	Broken	820.00 F	*820.00 FL
11	10		*FRONT GRILLE CLIPS	Necessary	25.00 F	*10.00 FL
12	1		*REINFORCEMENT	Not Necessary	1,200.70 F	*- FL
13	1		*FRONT LH HEADLAMP ASSY	Broken	2,719.60 F	*2,719.60 FL
14	1		*FRONT LH HEADLAMP BRACKET	Dented	132.00 F	*132.00 FL
15	1		*FRONT LH CORNER PANEL	Dented	587.90 F	*587.90 FL
16	1		*FRONT LH CORNER PANEL BRACKET	Dented	245.50 F	*245.50 FL
17	1		*FRONT LH REAR VIEW MIRROR ASSY	Broken	1,973.40 F	*1,973.40 FL
18	1		*FRONT LH SIDE GLASS	Broken	1,887.10 F	*1,887.10 FL
19	1		*LH SIDE PANEL	Dented	2,987.32 F	*2,987.32 FL
20	1		*FRONT LH LOWER INNER PILLAR PANEL	Dented	1,288.70 F	*1,288.70 FL
21	1		*LH SIDE INNER TRIM	Cut	752.70 F	*752.70 FL
22	1		*LH SIDE INNER GARNISH	Cut	569.20 F	*569.20 FL
23	1		*WATER TANK (WIPER)	Crushed	175.00 F	*175.00 FL
24	1		*WIPER ARM LH	Not Necessary	85.00 F	*- FL
25	1		*DASHBOARD	Not Necessary	3,986.40 F	*- FL
26	1		*FRONT LH MUD GUARD	Crushed	335.10 F	*335.10 FL
27	8		*SEALANT	Necessary	320.00 FS	*320.00 FS
28	1		*EXCURSION BUS STICKER	Necessary	15.00 FS	*15.00 FS
29	1		*RADIATOR ASSY	Not Necessary	2,899.04 F	*- FL
30	1		*INTER-COOLER ASSY	Not Necessary	2,653.50 F	*- FL
31	1		*WIPER TANK	Deformed	504.85 F	*504.85 FL
32	1		*WIPER MOTOR	Distorted	780.36 F	*780.36 FL
33	1		*HEATER UNIT	Cracked	2,218.74 F	*2,218.74 FL
34	1		*RADIATOR COWLING	Not Necessary	635.68 F	*- FL
35	1		*RADIATOR INLET	Not Necessary	239.75 F	*- FL
36	1		*AIRCON BLOWER CASING	Scratched	786.85 F	*786.85 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	40,614.69	28,894.62
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	2,855.96
Total Parts (\$\$)	40,614.69	26,038.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT DASHBOARD	New	350.00	350.00
2	REMOVE & REFIT LH SIDE GLASSES TO ASSIST REPAIR	New	360.00	360.00
3	REMOVE & REFIT FRONT WINDSCREEN	New	400.00	400.00
4	CHECK WIRING	New	100.00	90.00
5	LABOUR CHARGES	New	1,800.00	1,590.00
6	SPRAY PAINTING	New	1,000.00	900.00
Gross Labour Cost (\$)			4,010.00	3,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >