

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002113/BQY3N2**Date:** 10/06/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00103542100

Claimant Vehicle No : SFB9955D **Insured Vehicle No :** SFC2696S

Date of Loss: 04/03/2022 Nature of Claim: TP Claim No: SNM22D201569/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFB9955D**

Make & Model: HONDA FREED HYBRID, 1.5 G (A) Engine No: LEB5597923

Reg. Date: 30/05/2018 (Man. Year: 2018) Chassis No: GB71065251

Colour: Black Odometer: 123901 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,043.12	5,513.28	8,529.84	60.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,850.00	2,410.00	4,440.00	64.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,893.12	7,923.28	12,969.84	62.08
Approved Total (Overridden) (\$\$)		6,300.00		
(\$\$)	20,893.12	6,300.00	14,593.12	69.85
+ GST 7.00/7.00% (\$\$)	1,462.52	441.00	1,021.52	69.85
Nett Amount (\$\$)	22,355.64	6,741.00	15,614.64	69.85

INSPECTION

Date of Assignment: 07/06/2022

Date Inspected: 08/03/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFB9955D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,236.10 FL	*967.00 FL
2	1		*TAILGATE CENTRE EMBLEM	Necessary	32.50 FL	*32.50 FL
3	2		*TAILGATE CENTRE EMBLEM CLIPS	Not Necessary	10.00 FL	*- FL
4	1		*TAILGATE FREED EMBLEM	Necessary	63.00 FL	*44.70 FL
5	1		*TAILGATE HYBRID EMBLEM	Necessary	86.00 FL	*57.40 FL
6	1		*TAILGATE RH LAMP ASSY	Broken	362.00 FL	*362.00 FL
7	1		*TAILGATE RH LAMP GASKET	Necessary	18.50 FL	*18.50 FL
8	1		*TAILGATE LH LAMP ASSY	Broken	362.00 FL	*362.00 FL
9	1		*TAILGATE LH LAMP GASKET	Not Damaged	18.50 FL	*- FL
10	1		*TAILGATE CHROME MOULDING	Not Damaged	320.40 FL	*- FL
11	1		*TAILGATE WINDSCREEN GLASS RUBBER SEAL	Necessary	121.30 FL	*100.00 FL
12	1		*TAILGATE INNER TRIM BOARD	Broken	326.10 FL	*326.10 FL
13	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*30.00 FL
14	1		*TAILGATE LOCK	Jammed	189.40 FL	*118.00 FL
15	1		*TAILGATE LOCK CATCH	Not Damaged	54.10 FL	*- FL
16	1		*TAILGATE WEATHERSTRIP	Not Damaged	168.90 FL	*- FL
17	1		*TAILGATE INNER PULL POCKET HANDLE	Not Damaged	27.50 FL	*- FL
18	1		*TAILGATE OPENER SWITCH SENSOR	Not Damaged	268.90 FL	*- FL
19	1		*REAR BUMPER	Broken	1,017.50 FL	*981.00 FL
20	1		*REAR BUMPER RH SIDE REFLECTOR	Broken	54.80 FL	*54.80 FL
21	1		*REAR BUMPER LH SIDE RETAINER	Necessary	33.10 FL	*33.10 FL
22	1		*REAR BUMPER LH SIDE RETAINER	Necessary	33.10 FL	*33.10 FL
23	1		*REAR BUMPER LOWER COVER	No such part	279.30 FL	*- FL
24	1		*REAR BUMPER RH SIDE BRACKET	No such part	35.30 FL	*- FL
25	1		*REAR BUMPER LH SIDE BRACKET	No such part	35.30 FL	*- FL
26	1		*REAR BUMPER TOWING COVER	Not Damaged	28.30 FL	*- FL
27	1		*END PANEL (OUTER)	Dented	623.70 FL	*508.00 FL
28	1		*END PANEL (INNER)	Dented	453.80 FL	*351.20 FL
29	1		*END PANEL INNER TOP GARNISH	Broken	145.90 FL	*145.90 FL
30	1		*END RH SIDE PANEL	Not Damaged	397.10 FL	*- FL
31	1		*REAR LH FENDER INNER TRIM BOARD	Broken	547.80 FL	*386.10 FL
32	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FL	*30.00 FL
33	1		*REAR RH FENDER INNER TRIM BOARD	Broken	547.80 FL	*386.10 FL
34	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FL	*30.00 FL
35	1		*LH TAILLAMP	Not Damaged	651.80 FL	*- FL
36	1		*SET LH TAILLAMP LOCK CLIPS	Not Damaged	35.00 FL	*- FL
37	1		*RH TAILLAMP	Broken	651.80 FL	*481.60 FL
38	1		*SET RH TAILLAMP LOCK CLIPS	Necessary	35.00 FL	*20.00 FL
39	1		*REAR COMPARTMENT PANEL	Repair	1,056.80 FL	*- FL
40	1		*REAR COMPARTMENT PANEL INSULATOR	Not Necessary	343.00 FL	*- FL
41	1		*REAR COMPARTMENT PANEL TOP COVER BOARD	Not Necessary	699.40 FL	*- FL
42	1		*REAR COMPARTMENT PANEL MAT	Not Necessary	958.60 FL	*- FL
43	1		*EXHAUST SILENCER	Dented	723.20 FL	*588.00 FL
44	1		*EXHAUST SILENCER GASKET	Necessary	44.50 FL	*44.50 FL
45	1		*RH REAR FENDER	Repair	1,368.00 FL	*- FL
46	1		*EXHAUST SILENCER	Repeated	734.20 FL	*- FL

Report was unsubmitted during this print-out.

6/10/22, 1:50 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*EXHAUST SILENCER GASKET	Repeated	44.60 FL	*- FL
48	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	300.00 FS	*200.00 FS
49	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*40.00 FS
50	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	40.00 FS	*20.00 FS
51	1		*TAILGATE REVERSE CAMERA	Not Damaged	850.00 FS	*- FS
52	1		*END PANEL (OUTER) JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
53	1		*END PANEL (INNER) JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
54	1		*REAR COMPARTMENT PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
55	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
56	1		*RH REAR FENDER JOINT SEALANT	Not Necessary	70.00 FS	*- FS
57	1		*REAR LH FENDER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
58	1		*REAR LH FENDER GLASS INNER SEAL	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,123.90	6,811.60
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,080.78	1,298.32
Total Parts (\$\$)					14,043.12	5,513.28
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,500.00	1,200.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,300.00	900.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	0.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	200.00	120.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	120.00	0.00
7	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	120.00	80.00
8	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH AND BOARDS TO ASSIST REPAIR	New	280.00	0.00
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	150.00	50.00
10	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
11	LABOUR CHARGES	New	1,200.00	0.00
12	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODE	New	1,000.00	0.00
13	REMOVE AND REINSTALL RH REAR FENDER GLASS	New	180.00	0.00
14	REMOVE AND REINSTALL ROOF LINING,SEAT AND CARPET TO ASSIST REPAIR	New	380.00	0.00
15	REMOVE AND REINSTALL FUEL TANL,PIPE AND SENSORS TO ASSIST REPAIR	New	120.00	0.00
Gross Labour Cost (\$)			6,850.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >