



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 6337L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	MTG CRACKED	801.20	762.70
2	FRONT BUMPER RETAINER @\$20.80	N/S DISTORTED	41.20	20.60
10	FRONT BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	N/S FRONT FENDER	BENT	421.80	421.80
1	N/S FRONT FENDER ARCH GARNISH	DENTED	153.20	153.20
1	N/S HEAD LAMP	MTG CRACKED	1,923.40	1,859.00
	LESS 20% DISCOUNT		-675.16	-650.46
			2,700.64	2,601.84
1	N/S FRONT WHEEL RIM (SN)	DENTED	833.30	550.00
	LESS 20% DISCOUNT		-166.66	-
			666.64	550.00
<u>LABOUR</u>				
	TO PUTTY & SPRAY PAINT.		700.00	600.00
	TO CHECK WIRING & FOCUS HEAD LIGHTS.		30.00	20.00
	TO CHECK WHEEL ALIGNMENT.		60.00	60.00
	TO ANTI RUST.		50.00	30.00
	LABOUR CHARGES.		600.00	400.00
			1,440.00	1,110.00
GRAND TOTAL			4,807.28	4,261.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,350.00

Report Ref No. CS/UOI22002116/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.