

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22002118/KVY3E2

Date: 05/04/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001673309
Claimant Vehicle No :	SHA4749Y	Insured Vehicle No :	SMY5109C
Date of Loss:	04/03/2022	Nature of Claim:	TP
		Claim No:	270816

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4749Y	Engine No:	G4LEKU211298
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU146232
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	388148 km
Colour:	Light Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,226.03	4,649.92	6,576.11	58.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,460.00	2,030.00	3,430.00	62.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,686.03	6,679.92	10,006.11	59.97
+ GST 7.00/7.00% (S\$)	1,168.02	467.59	700.43	59.97
Nett Amount (S\$)	17,854.05	7,147.51	10,706.54	59.97

INSPECTION

Date of Assignment:	08/03/2022	
Date Inspected:	08/03/2022	Inspected At: Blk 9 Sector C #01-42, Sin Ming Industrial Estate, Repairer: Bifrost Auto Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2022)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4749Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (RH)	Bent	1,789.90 FL	*1,789.90 FL
2	1		*REAR DOOR OUTER HANDLE (RH)	Serviceable	124.80 FL	*- FL
3	1		*REAR DOOR GEAR / REGULATOR (RH)	Serviceable	367.84 FL	*- FL
4	1		*REAR DOOR POWER MOTOR (RH)	Serviceable	256.80 FL	*- FL
5	1		*REAR DOOR LOCK ASSY	Repair	306.40 FL	*- FL
6	1		*REAR DOOR TRIM BOARD (RH)	Serviceable	613.60 FL	*- FL
7	1		*REAR DOR PROTECTOR (RH)	Dented	166.20 FL	*166.20 FL
8	1		*ROCKER PANEL OUTER GARNISH	Serviceable	715.60 FL	*- FL
9	1		*ROCKER PANEL OUTER GARNISH CLIP	Not Necessary	65.00 FL	*- FL
10	1		*REAR BUMPER	Repair	459.40 FL	*- FL
11	1		*REAR BUMPER STAY	Serviceable	138.10 FL	*- FL
12	1		*REAR BUMPER SIDE RETAINER (RH)	Serviceable	85.80 FL	*- FL
13	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
14	1		*REAR FENDER (RH)	Bent	1,768.30 FL	*1,768.30 FL
15	2		*REAR FENDER SHIELD REAR PIECE (LH/RH)	Not Necessary	173.60 FL	*- FL
16	1		*REAR FENDER SHIELD FRT PIECE (RH)	Serviceable	165.50 FL	*- FL
17	1		*REAR TYRE RIM (RH)	Serviceable	1,124.20 FL	*- FL
18	1		*REAR WHEEL HUP-CAP (RH)	Dented	346.40 FL	*346.40 FL
19	1		*REAR WHEELBEARING & HUB ASSY	Not Necessary	554.00 FL	*- FL
20	1		*REAR TRAILING ARM (RH)	Serviceable	265.40 FL	*- FL
21	1		*REAR ASSIST (RH)	Distorted	227.90 FL	*227.90 FL
22	1		*REAR SHOCK ABSORBER (RH)	Bent	230.50 FL	*230.50 FL
23	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Serviceable	133.10 FL	*- FL
24	1		*REAR ABSORBER STOPPER (RH)	Serviceable	137.60 FL	*- FL
25	1		*REAR ABSORBER COVER (RH)	Serviceable	175.60 FL	*- FL
26	1		*REAR CROSSMEMBER	Serviceable	1,468.70 FL	*- FL
27	1		*STABILIZER BAR	Serviceable	387.30 FL	*- FL
28	1		*STABILIZER LINK (RH)	Serviceable	147.30 FL	*- FL
29	1		*REAR UPPER ARM (RH)	Distorted	239.50 FL	*239.50 FL
30	1		*REAR LOWER ARM (RH)	Bent	393.10 FL	*393.10 FL
31	1		*REAR KNUCKLE ARM (RH)	Bent	538.10 FL	*538.10 FL
32	1		*REAR DOOR TEL NO. STICKER (RH)	Necessary	10.00 FS	*10.00 FS
33	1		*REAR DOOR COMFORDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
34	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
35	1		*REAR TYRE (RH)	Serviceable	216.00 FS	*- FS
					Sub Total (\$\$)	13,943.54 5,789.90
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,717.51 1,139.98
					Total Parts (\$\$)	11,226.03 4,649.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	100.00	20.00
4	TUFF KOTE	New	100.00	60.00
5	TOWING CHARGE	New	80.00	50.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	100.00
7	REMOVE / REFIX UNDERCARRIAGE (RR)	New	400.00	180.00
8	RE-SET REAR ABS SYSTEM	New	400.00	0.00
9	REMOVE / REFIX FUEL TANK	New	80.00	0.00
10	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
11	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
12	FOUR WHEEL ALIGNMENT	New	120.00	60.00
13	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			5,460.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >