

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1008L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CUT	553.00	553.00
1	REAR BUMPER UNDER COVER	SCRATCHED	228.00	228.00
1	REAR BUMPER SPONGE	SERVICEABLE	119.50	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	REAR BUMPER REFLECTOR (RH/LH) @\$32.00	O/S CRACKED / N/S SERVICEABLE	64.00	32.00
	LESS 20% DSICOUNT		-282.98	-167.00
			1,131.92	668.00
NETT ITEMS				
1	REVERSE SENSORS (N)	CUT	135.70	135.70
	LESS 10% DISCOUNT		-13.57	-13.57
			122.13	122.13
LABOUR				
	PANEL BEATING.		300.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	R/I REVERSE SENSORS.		120.00	30.00
			720.00	560.00
GRAND TOTAL			1,974.05	1,350.13
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,100.00

Report Ref No. NS/INC22002127/Vvcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.