

Ref: (B): Thuvan / Ref: Nil

**COMFORTDELGRO ENGINEERING PTE LTD**

Effective Date: 1 Nov 2020

**REPAIR ESTIMATE**

LKK-

DATE: 17-Feb-22

INSURANCE: NTUC (L/S)

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SHC1008L

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$553.00 /cut
	Rear Bumper Under Cover	1		\$228.00 /scr
	Rear Bumper Sponge	1		\$119.50 /XSC
	Rear Bumper Reinforcement	1		\$428.40 /XSC
	Rear Bumper Clips	10	\$2.20	\$22.00 /MC
	Rear Bumper Reflector (RH/LH) XSC	2	\$32.00 /im	\$64.00 XSC
	<b>SUB TOTAL</b>			\$1,414.90
	<b>LESS 20% DISCOUNTED TOTAL</b>			\$282.98
				<b>\$1,131.92</b>
	Reverse Sensors	1		\$135.70 /cut
	<b>NETT SUB</b>			\$135.70
	<b>LESS 10%</b>			\$13.57
	<b>NETT TOTAL</b>			<b>\$122.13</b>
	<b>SPARE PARTS TOTAL</b>			<b>\$1,254.05</b>
	<b>Labour Charge</b>			
	Panel Beating			\$300.00 280
	Spray Painting Charge			\$300.00 250
	R/I Reverse Sensors			\$120.00 30
	<b>TOTAL LABOUR</b>			<b>\$720.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$1,974.05</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuvan 82235764  
 17/2/22 1630  
 L/S after repair photo  
 2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: