

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1670J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	CUT	553.00	553.00
1	REAR BUMPER LOWER COVER	SCRATCHED	228.00	228.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET LH	NECESSARY	35.60	35.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	32.00	-
	LESS 20% DISCOUNT		-259.80	-167.72
			1,039.20	670.88
	NETT ITEMS			
1	REAR REVERSE SENSOR (N)	CUT	135.70	135.70
1	REAR BUMPER PROTECTOR (N)	NECESSARY	50.00	50.00
	LESS 10% DISCOUNT		-18.57	-18.57
			167.13	167.13
	<u>LABOUR</u>			
	PANEL BEATING.		420.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
	CHECK LIGHTING & WIRING.		40.00	20.00
			820.00	570.00
	GRAND TOTAL		2,026.33	1,408.01
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,100.00

Report Ref No. NS/INC22002129/Vvcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser