

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22002133/EGA3Q2**Date:** 17/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SMT2338D **Insured Vehicle No :** SLU2632K

Date of Loss: 04/03/2022 Nature of Claim: TP Claim No: MFL2022D0001128

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT2338D**

Make & Model: BMW 116D, 1.5 D 5DR HATCH DSC LED (A) Engine No: 32319768B37D15A

Reg. Date: 16/03/2017 (Man. Year: 2016) Chassis No: WBA1V72080V725535

Colour: White Odometer: 69994 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,535.00	1,870.00	665.00	26.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,827.00	3,862.00	965.00	19.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,362.00	5,732.00	1,630.00	22.14
+ GST 7.00/7.00% (S\$)	515.34	401.24	114.10	22.14
Nett Amount (S\$)	7,877.34	6,133.24	1,744.10	22.14
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,390.69		

INSPECTION

Date of Assignment: 08/03/2022

Date Inspected: 29/03/2022 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance
Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2022)

Parts: 144 BMW 116D 1.5 D 5DR HATCH DSC LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMT2338D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Dented	418.55 FS	*418.55 FS
3	1		*REAR BUMPER CENTRE GUIDE (M)	Broken	153.50 FS	*153.50 FS
4	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	39.35 FS	*- FS
5	1		*REAR BUMPER RH MOUNT	Not Necessary	141.05 FS	*- FS
6	1		*REAR BUMPER PRIMED (RFC)	Dented	1,004.85 FS	*1,004.85 FS
7	1		*SET REAR PDC HOLDER	Necessary	25.75 FS	*25.75 FS
8	2		*EMBLEM GROMMET	Not Necessary	1.90 FS	*- FS
9	1		*HEAT INSULAT	Not Necessary	73.60 FS	*- FS
10	1		*PLAQUE 82MM	Necessary	72.85 FS	*72.85 FS
11	1		*RH REFLECTOR	Not Necessary	37.90 FS	*- FS
12	2		*NUMBER PLATE LIGHT LED	Dented	56.30 FS	*56.30 FS
13	1		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	5.15 FS	*5.15 FS
14	1		*PDC SENSOR MINERALWEISS (A96)	Not Necessary	371.20 FS	*- FS
15	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
					Total Parts (S\$)	2,535.00 1,870.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER INCLUDING TO KNOCK OUT BOOT LID AND DENTED AREA	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	1,923.00	1,826.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (\$\$)			4,827.00	3,862.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >