

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002140/UGA3Q2**Date:** 08/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210143820
Claimant Vehicle No :	SLN6244H	Insured Vehicle No :	SNC9504Y
Date of Loss:	07/03/2022	Nature of Claim:	TP
		Claim No:	5628233706SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN6244H	Engine No:	P520352312
Make & Model:	MAZDA 2, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	MM6DL2SAAGW197166
Reg. Date:	11/05/2017 (Man. Year: 2016)	Odometer:	76443 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R16	Rear Tyre Size:	185/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,466.16	5,498.00	2,968.16	35.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	2,330.00	2,040.00	46.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,836.16	7,828.00	5,008.16	39.02
Approved Total (Overridden) (S\$)		6,250.00		
Nett Amount (S\$)	12,836.16	6,250.00	6,586.16	51.31
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		6,757.49		

INSPECTION

Date of Assignment:	08/03/2022		
Date Inspected:	08/03/2022	Inspected At:	Soon San Motor Trading (HQ) BLK 3006 UBI ROAD 1 #01-390 Singapore 408700
Estimated Period of Repair:	8.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Badly Dented	861.80 FL	*861.80 FL
2	1		*BOOT LID HINGES	Repair	231.00 FL	*- FL
3	1		*BOOT LID EMBLEM	Necessary	58.80 FL	*58.80 FL
4	1		*BOOT LID SKYACTIV PLATE	Necessary	67.60 FL	*67.60 FL
5	1		*BOOT LID MAZDA PLATE	Necessary	57.90 FL	*57.90 FL
6	1		*BOOT LID TOP LOCK	Bent	190.90 FL	*190.90 FL
7	1		*BOOT LID LOWER LOCK	Not Necessary	35.10 FL	*- FL
8	1		*BOOT LID LOWER SWITCH	Cracked	209.20 FL	*209.20 FL
9	1		*BOOT LID RUBBER	Twisted	112.90 FL	*112.90 FL
10	2		*BOOT LID REFLECTORS	Cracked	416.40 FL	*380.00 FL
11	1		*BOOT LID INSULATOR	Deformed / Torn	302.60 FL	*302.60 FL
12	2		*TAIL LAMPS	Cracked	790.60 FL	*790.60 FL
13	2		*TAIL LAMP INNER PANELS	Bent	575.40 FL	*500.00 FL
14	6		*TAIL LAMP INNER CLIPS	Not Necessary	48.00 FL	*- FL
15	1		*REAR PANEL	Badly Dented	656.00 FL	*600.50 FL
16	1		*REAR PANEL INNER COVER	Twisted	210.70 FL	*210.70 FL
17	2		*REAR FENDERS INNER TRIM COVERS	Deformed / Twisted	565.00 FL	*565.00 FL
18	1		*REAR EXHAUST PIPE	Repair	1,026.80 FL	*- FL
19	1		*REAR EXHAUST PIPE OUTER CHROME	Serviceable	180.00 FL	*- FL
20	2		*REAR EXHAUST PIPE RUBBER HOLDERS	Not Necessary	90.00 FL	*- FL
21	1		*REAR BUMPER	Distorted	954.50 FL	*945.00 FL
22	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	320.00 FS	*200.00 FS
23	2		*REAR BUMPER REFLECTORS	Cracked	106.00 FL	*106.00 FL
24	2		*REAR BUMPER TOP SIDE CLIPS	Not Necessary	20.00 FL	*- FL
25	2		*REAR BUMPER SIDE HOLDERS	Bent	91.60 FL	*91.60 FL
26	1		*SET REAR BUMPER INNER CLIPS	Necessary	80.00 FL	*50.00 FL
27	1		*REAR BUMPER REINFORCEMENT	Not fitted	198.20 FL	*- FL
28	2		*REAR BUMPER INNER BRACKETS	Not fitted	136.80 FL	*- FL
29	1		*SPARE TYRE PANEL	Repair	1,102.50 FL	*- FL
30	1		*SPARE TYRE PANEL PADDLING	Not Necessary	285.00 FL	*- FL
31	1		*REAR TOOL HOLDER SPONGE CENTRE	Torn	198.00 FL	*198.00 FL
32	1		*REAR SPONGE LEFT	Torn	69.30 FL	*69.30 FL
33	1		*REAR SPONGE RIGHT	Torn	56.00 FL	*56.00 FL
34	1		*REAR SARE TYRE TOP COVER	Torn	198.10 FL	*198.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,502.70	6,822.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,036.54	1,324.50
Total Parts (\$\$)	8,466.16	5,498.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUSTPROOF	New	300.00	80.00
2	TO CHECK WIRING	New	50.00	20.00
3	TO DISMANTLE /RENEW REVERSE SENSORS	New	100.00	50.00
4	TO REMOVE/REFIT REAR INTERIOR TO EFFECT REPAIR	New	120.00	80.00
5	TO DISMANTLE /RENEW EXHAUST PIPE	New	100.00	0.00
6	TO REMOVE/REFIT REVERSE CAMERA	New	100.00	0.00
7	TO DISMANTLE /RENEW ACCIDENT PORTION	New	1,800.00	1,000.00
8	TO SPRAY PAINT	New	1,800.00	1,100.00
Gross Labour Cost (\$)			4,370.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >