

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002143/EVY3N2**Date:** 06/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00056412101

Claimant Vehicle No : SBA788G **Insured Vehicle No :** GBK206S

Date of Loss: 04/03/2022 Nature of Claim: TP Claim No: SNM22D201589/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBA788G**

Make & Model: MERCEDES-BENZ E200, 2.0 (A) Engine No: 26492030451969

Reg. Date: 17/11/2021 (Man. Year: 2021) Chassis No: W1K2130802B003984

Colour: Silver Odometer: 5406 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18 Rear Tyre Size: 245/45R18

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,927.39	2,778.94	1,148.45	29.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	2,140.00	680.00	24.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,747.39	4,918.94	1,828.45	27.10
+ GST 7.00/7.00% (\$\$)	472.32	344.33	127.99	27.10
Nett Amount (\$\$)	7,219.71	5,263.27	1,956.44	27.10

INSPECTION

Date of Assignment: 29/03/2022

Date Inspected: 21/03/2022 Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBA788G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,093.33 FS	*2,093.33 FS
2	1		*REAR BOTTOM PANEL	Cut	329.97 FS	*329.97 FS
3	1		*REAR BOTTOM PANEL GARNISH	Necessary	355.64 FS	*355.64 FS
4	1		*CT/R BASIC CARRIER FOR BUMPER	Not Necessary	110.11 FS	*- FS
5	1		*LH/R BASIC CARRIER FOR BUMPER	Not Necessary	56.55 FS	*- FS
6	1		*RH/R BASIC CARRIER FOR BUMPER	Not Necessary	56.55 FS	*- FS
7	1		*REAR CROSS MEMBER	Not Necessary	925.24 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					3,927.39	2,778.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH	New	1,440.00	960.00
3	RESPRAY REAR BUMPER	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,820.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >