

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002149/AVY3N2**Date:** 23/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00088362102		
Claimant Vehicle No :	SMJ4881R	Insured Vehicle No :	YN6051T		
Date of Loss:	07/03/2022	Nature of Claim:	TP	Claim No:	SNM22D201593/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ4881R		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5562519
Reg. Date:	07/03/2019 (Man. Year: 2018)	Chassis No:	RU11312501
Colour:	Grey	Odometer:	102455 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,779.32	5,254.04	1,525.28	22.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,060.00	550.00	34.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,389.32	6,314.04	2,075.28	24.74
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	8,389.32	5,000.00	3,389.32	40.40
+ GST 7.00/7.00% (\$\$)	587.25	350.00	237.25	40.40
Nett Amount (\$\$)	8,976.57	5,350.00	3,626.57	40.40

INSPECTION

Date of Assignment:	08/03/2022	
Date Inspected:	08/03/2022 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ4881R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	892.30 FL	*892.30 FL
2	2		*FRONT BONNET HINGES L/R	Not Necessary	97.00 FL	*- FL
3	2		*FRONT BONNET INNER RUBBER GUIDE STOPPER L/R	Not Necessary	47.60 FL	*- FL
4	2		*FRONT BONNET INNER SIDE MOULDING L/R	Not Necessary	75.00 FL	*- FL
5	2		*FRONT BONNET INNER TOP MOULDING L/R	Not Necessary	66.00 FL	*- FL
6	1		*FRONT BONNET MECHANISM LOCK	Not Necessary	95.00 FL	*- FL
7	1		*FRONT BUMPER	Deformed	927.50 FL	*765.00 FL
8	2		*FRONT BUMPER FOGLAMP GARNISH L/R	Not Necessary	90.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	77.50 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	321.00 FL	*321.00 FL
11	2		*FRONT BUMPER REINFORCEMENT TOP MOULDING L/R	Not Necessary	70.00 FL	*- FL
12	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	41.20 FL	*- FL
13	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	17.10 FL	*- FL
14	2		*FRONT FENDER ARCH GARNISH L/R	Not Necessary	330.00 FL	*- FL
15	1		*FRONT GRILLE	Cracked	351.80 FL	*351.80 FL
16	1		*FRONT GRILLE LOGO EMBLEM	Necessary	23.40 FL	*23.40 FL
17	1		*FRONT GRILLE CENTER BRACKET	Cracked	76.00 FL	*76.00 FL
18	1		*FRONT GRILLE OUTER COVER	Cracked	421.00 FL	*421.00 FL
19	1		*FRONT GRILLE TOP GARNISH	Cracked	85.00 FL	*85.00 FL
20	2		*FRONT HEADLAMP CHROME MOULDING L/R	Not Necessary	217.80 FL	*- FL
21	2		*FRONT HEADLAMP L/R	Cracked	3,430.80 FL	*3,430.80 FL
22	2		*FRONT HEADLAMP LOWER BRACKET L/R	Cracked	70.00 FL	*70.00 FL
23	2		*FRONT HEADLAMP SIDE BRACKET L/R	Not Necessary	70.00 FL	*- FL
24	1		*FRONT HORN	Not Necessary	110.50 FL	*- FL
25	1		*FRONT TOP PANEL	Repair	176.90 FL	*- FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
27	2		*SET FRONT FENDER ARCH GARNISH CLIPS L/R	Not Necessary	60.00 FS	*- FS
28	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
29	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
30	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,415.40	6,541.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,636.08	1,287.26
Total Parts (\$\$)	6,779.32	5,254.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING (TO FR)	New	50.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	500.00
3	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	500.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	60.00	30.00
Gross Labour Cost (\$)			1,610.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >