

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002150/AQY3N2**Date:** 25/05/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00126152100
Claimant Vehicle No : SLN5015J **Insured Vehicle No :** GBL5395R
 Date of Loss: 05/03/2022 Nature of Claim: TP Claim No: SNM22D201591/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN5015J**
 Make & Model: HONDA CITY, 1.5 CVT (A) Engine No: L15Z14118254
 Reg. Date: 05/05/2017 (Man. Year: 2016) Chassis No: MRHGM6660HT000129
 Colour: White Odometer: 111234 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55R16 Rear Tyre Size: 185/55R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,299.80	7,196.76	3,103.04	30.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	3,330.00	1,000.00	23.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,629.80	10,526.76	4,103.04	28.05
Approved Total (Overridden) (S\$)		8,400.00		
(S\$)	14,629.80	8,400.00	6,229.80	42.58
+ GST 7.00/7.00% (S\$)	1,024.09	588.00	436.09	42.58
Nett Amount (S\$)	15,653.89	8,988.00	6,665.89	42.58

INSPECTION

Date of Assignment: 08/03/2022
 Date Inspected: 07/03/2022 Inspected At: N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
 #01-18 KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2
 Singapore 417921
 Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2022)
Parts: 143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN5015J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Distorted	622.30 FL	*622.30 FL
2	1		*REAR BOOTLID CITY EMBLEM	Necessary	21.90 FL	*21.90 FL
3	1		*REAR BOOTLID I-VTEC EMBLEM	Necessary	21.90 FL	*21.90 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	31.80 FL	*31.80 FL
5	2		*REAR BOOTLID HINGES L/R	Bent	159.60 FL	*159.60 FL
6	2		*REAR BOOTLID INNER RUBBER STOPPER (LONG) L/R	Not Necessary	40.00 FL	*- FL
7	2		*REAR BOOTLID INNER RUBBER STOPPER L/R	Not Necessary	19.60 FL	*- FL
8	1		*REAR BOOTLID INNER TRIM BOARD	Torn	99.70 FL	*99.70 FL
9	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	39.40 FL	*- FL
10	1		*REAR BOOTLID MECHANISM LOCK	Damaged	105.20 FL	*105.20 FL
11	2		*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	56.80 FL	*- FL
12	1		*REAR BOOTLID OUTER CHROME HANDLE	Cracked	165.20 FL	*165.20 FL
13	1		*REAR BOOTLID OUTER LOCK SWITCH WITH CAMERA	Damaged	625.90 FL	*625.90 FL
14	2		*REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R	Necessary	50.00 FL	*50.00 FL
15	2		*REAR BOOTLID REFLECTOR L/R	Cracked	197.20 FL	*197.20 FL
16	1		*REAR BOOTLID WEATHER STRIP	Cut	84.20 FL	*84.20 FL
17	1		*REAR BUMPER	Distorted	463.70 FL	*463.70 FL
18	2		*REAR BUMPER REFLECTOR L/R	Cracked	96.40 FL	*96.40 FL
19	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	47.80 FL	*47.80 FL
20	1		*REAR END PANEL	Distorted	395.80 FL	*395.80 FL
21	1		*REAR END PANEL ANTENNA SENSOR	Cracked	78.10 FL	*78.10 FL
22	1		*REAR END PANEL BUZZLE SENSOR	Cracked	95.20 FL	*95.20 FL
23	1		*REAR END PANEL INNER TOP GARNISH	Cracked	86.20 FL	*86.20 FL
24	1		*REAR EXHAUST GASKET	Not Necessary	19.20 FL	*- FL
25	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	37.40 FL	*- FL
26	1		*REAR EXHAUST SILENCER BOX	Not Necessary	580.20 FL	*- FL
27	2		*REAR FENDER INNER PANEL L/R	Repair	918.40 FL	*- FL
28	2		*REAR FENDER INNER SHIELD L/R	Torn	299.60 FL	*299.60 FL
29	2		*REAR FENDER INNER TRIM BOARD L/R	Torn	198.60 FL	*198.60 FL
30	1		*REAR FENDER L/R	O/s Buckled	2,218.80 FL	*1,109.40 FL
31	1		*REAR FLOOR LOWER JACK PANEL	Buckled	289.00 FL	*289.00 FL
32	1		*REAR FLOOR PANEL	Buckled	560.20 FL	*560.20 FL
33	1		*REAR FLOOR PANEL TOP BOARD COVER	Torn	129.40 FL	*129.40 FL
34	2		*REAR TAILLAMP INNER BLACK GASKET L/R	Necessary	50.00 FL	*50.00 FL
35	2		*REAR TAILLAMP INNER PANEL L/R	Buckled	185.40 FL	*185.40 FL
36	2		*REAR TAILLAMP INNER VERTICAL PANEL L/R	Buckled	538.00 FL	*179.60 FL
37	2		*REAR TAILLAMP L/R	Cracked	651.40 FL	*651.40 FL
38	1		*REAR WINDSCREEN	Cut	739.20 FL	*739.20 FL
39	1		*REAR WINDSCREEN MOULDING	Necessary	149.80 FL	*149.80 FL
40	1		*REAR BOOTLID LOGO EMBLEM CLIPS - SET	Necessary	30.00 FS	*10.00 FS
41	1		*REAR BOOTLID INNER TRIM BOARD CLIPS - SET	Necessary	50.00 FS	*20.00 FS
42	1		*REAR BOOTLID NUMBER PLATE	Bent	25.00 FS	*25.00 FS
43	1		*REAR BOOTLID NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
44	1		*REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET	Necessary	50.00 FS	*20.00 FS
45	1		*REAR BUMPER CLIPS - SET	Necessary	80.00 FS	*30.00 FS
46	1		*REAR BUMPER REVERSE SENSOR (4PC) - SET	Damaged	400.00 FS	*300.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR END PANEL INNER TOP GARNISH CLIPS - SET	Necessary	40.00 FS	*10.00 FS
48	2		*REAR FENDER INNER SHIELD CLIPS L/R -SET	Necessary	100.00 FS	*20.00 FS
49	2		*REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	Necessary	100.00 FS	*60.00 FS
50	1		*REAR FLOOR PANEL INSULATOR MAT - SET	Necessary	300.00 FS	*200.00 FS
51	2		*REAR TAILLAMP CLIPS L/R - SET	Necessary	60.00 FS	*20.00 FS
52	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,533.50	8,794.70
- List Item Discount on L Items 20.00/20.00% (\$)	2,233.70	1,597.94
Total Parts (\$)	10,299.80	7,196.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	80.00	80.00
2	TO REMOVE, REINSTALL WINDSCREEN (REAR)	New	150.00	120.00
3	TO REMOVE, REINSTALL PETROL TANK. (TO FR)	New	80.00	60.00
4	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	120.00	60.00
5	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.	New	1,400.00	1,200.00
6	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	New	100.00	60.00
7	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	2,200.00	1,600.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACE PANEL.	New	120.00	100.00
9	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	50.00
			Gross Labour Cost (\$\$)	4,330.00
				3,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >