



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 3973J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP ASSY-LH (N)	CRACKED	2,772.00	2,772.00
1	FRONT BUMPER (N)	BENT	1,495.00	1,495.00
1	FRONT BUMPER SIDE RETAINER-LH (N)	SERVICEABLE	38.00	-
1	FRONT BUMPER FOG LAMP COVER-LH (N)	DENTED	78.00	78.00
1	FRONT BUMPER LOWER SKIRT-LH (N)	SERVICEABLE	152.00	-
1	FRONT BUMPER SENSOR (N)	SHORTED	205.00	205.00
6	FRONT BUMPER SENSOR SEALS @\$12.00 (N)	NECESSARY	72.00	72.00
1	FRONT FENDER WHEEL ARCH GARNISH-LH (N)	SERVICEABLE	235.00	-
	LESS 10% DISCOUNT		-504.70	-462.20
			4,542.30	4,159.80
	<u>LABOUR</u>			
	TO REMOVE AND REFIT FRONT BUMPER SENSOR.		100.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER,LH FRONT CHASSIS FRAME,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME.		800.00	250.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		800.00	250.00
	TO APPLY RUST PROOFING ON REPLACED AND REPAIRED PANELS.	NOT NECESSARY	80.00	-
	TO PROGRAM & RESET HEADLAMP FAULT CODE.		200.00	200.00
			2,060.00	780.00
	GRAND TOTAL		6,602.30	4,939.80
	RECOMMENDED COST OF REPAIRS			4,939.80

Report Ref No. CS/AGI22002151/Kty3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.