

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002155/KVY3Q2**Date:** 01/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00013592207

Claimant Vehicle No : SJY6020C **Insured Vehicle No :** GBD6734G

Date of Loss: 02/03/2022 Nature of Claim: TP Claim No: SNM22D201529/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY6020C**

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZY106637

Reg. Date: 17/09/2010 (Man. Year: 2010) Chassis No: MR053HY9305169795

Colour: Metallic Green Odometer: 173279 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 8 mm Rear Left Side: Nexen 4 mm

Front Right Side: Nexen 8 mm Rear Right Side: Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,747.20	2,977.53	4,769.67	61.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	1,380.00	1,910.00	58.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,037.20	4,357.53	6,679.67	60.52
Approved Total (Overridden) (\$\$)		3,150.00		
(\$\$)	11,037.20	3,150.00	7,887.20	71.46
+ GST 7.00/7.00% (\$\$)	772.60	220.50	552.10	71.46
Nett Amount (\$\$)	11,809.80	3,370.50	8,439.30	71.46

INSPECTION

Date of Assignment: 08/03/2022

Date Inspected: 08/03/2022 Inspected At: Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY6020C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT EMBLEM LOGO	Necessary	83.50 F	*45.70 FL
2	1		*BOOT EMBLEM VIOS	Necessary	73.50 F	*42.50 FL
3	1		*BOOT EMBLEM E	Necessary	73.50 F	*42.50 FL
4	1		*BOOT HINGE -LH	Repair	100.00 F	*- FL
5	1		*BOOT HINGE -RH	Repair	100.00 F	*- FL
6	1		*BOOT LOCK	Dented	185.10 F	*185.10 FL
7	1		*BOOT OUTER GARNISH	Warped	251.40 F	*251.40 FL
8	1		*BOOT TOP LOCK	Repair	90.95 F	*- FL
9	1		*BOOT LID	Bent	656.95 F	*656.95 FL
10	1		*BOOT LID WEATHERSTRIP (50%)	Cut	165.62 FS	*82.81 FS
11	1		*EXHAUST MUFFLER	Repair	538.10 F	*- FL
12	1		*REAR BODY PANEL	Bent	503.30 F	*503.30 FL
13	1		*REAR BODY PANEL TOP GARNISH	Dented	200.76 F	*200.76 FL
14	1		*REAR BUMPER	Bent	529.50 F	*529.50 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	6.00 F	*6.00 FL
16	1		*REAR BUMPER REFLECTOR -LH	Cracked	162.50 F	*135.00 FL
17	1		*REAR BUMPER REFLECTOR -RH	Cracked	162.50 F	*135.00 FL
18	1		*REAR BUMPER SIDE RETAINER -LH	Serviceable	73.05 F	*- FL
19	1		*REAR BUMPER SIDE RETAINER -RH	Distorted	78.05 F	*78.05 FL
20	1		*REAR FENDER INNER TRIM -LH	Serviceable	369.50 F	*- FL
21	1		*REAR FENDER INNER TRIM -RH	Serviceable	369.50 F	*- FL
22	1		*REAR NUMBER PLATE LAMP -LH	Serviceable	103.90 F	*- FL
23	1		*REAR NUMBER PLATE LAMP -RH	Serviceable	103.90 F	*- FL
24	1		*REAR TOOL BOX	Cracked	138.00 F	*138.00 FL
25	1		*REAR WHEEL PANEL COVER	Cracked	299.50 F	*299.50 FL
26	1		*SPARE WHEEL PANEL	Repair	497.62 F	*- FL
27	1		*TAIL LAMP LH	Serviceable	297.60 F	*- FL
28	1		*TAIL LAMP RH	Cracked	297.60 F	*283.70 FL
29	1		*TAILLAMP PANEL -LH	Repair	138.00 F	*- FL
30	1		*TAILLAMP PANEL -RH	Repair	138.00 F	*- FL
31	1		*SET REAR BODY GARNISH CLIP	Not Necessary	10.00 F	*- FL
32	1		*REAR SPARE TYRE PANEL SPONGE -LH	Serviceable	155.90 F	*- FL
33	1		*REAR SPARE TYRE PANEL SPONGE -RH	Serviceable	155.90 F	*- FL
34	1		*REAR SPARE TYRE PANEL SPONGE -CENTRE	Serviceable	288.00 F	*- FL
35	1		*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
36	1		*REVERSE SENSORS	Dented	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,747.20	3,860.77
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	883.24
Total Parts (\$\$)	7,747.20	2,977.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,500.00	600.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,500.00	700.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	150.00	60.00
4	TO REMOVE/RENEW EXHAUST MUFFLER	New	100.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	40.00	20.00
Gross Labour Cost (\$)			3,290.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >