



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7882P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER COVER	BROKEN	430.90	430.90
1	FRONT RH BUMPER RETAINER	NOT NECESSARY	28.00	-
1	FRONT RH BUMPER SIDE SUPPORT BRACKET	NOT NECESSARY	12.00	-
1	FRONT BUMPER ENERGY ABSORBER	NOT NECESSARY	86.90	-
1	FRONT RH BUMPER MOULDING	NOT NECESSARY	93.00	-
1	FRONT RH FOG LAMP	NOT NECESSARY	642.50	-
1	FRONT RH BUMPER AIR CURTAIN DUCT	NOT NECESSARY	56.50	-
1	WIPER RESERVOIR	NOT NECESSARY	150.80	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	1,075.10	-
1	FRONT BUMPER UPPER CENTER MOULDING	NOT NECESSARY	284.90	-
1	FRONT BUMPER UNDERTRAY COVER	NOT NECESSARY	469.40	-
1	FRONT RH HEADLAMP	CUT	2,110.30	2,110.30
1	FRONT RH HEADLAMP COMPUTER	NOT NECESSARY	841.80	-
1	FRONT RH FENDER PANEL	DENTED	588.80	588.80
1	FRONT RH FENDER LINER	TORN	114.70	114.70
1	FRONT RH FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRONT RH FENDER AND BUMPER MOUNTING BRACKET	NOT NECESSARY	39.30	-
1	FRONT END MODULE CARRIER	NOT NECESSARY	949.30	-
	LESS 20% DISCOUNT		-1,600.16	-654.26
			6,400.64	2,617.04
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	75.00	25.00
1	SET FRONT BUMPER RIVET (SN)	NECESSARY	65.00	10.00
1	FRONT BUMPER UNDERTRAY COVER CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRONT FENDER LINER CLIP (SN)	NECESSARY	65.00	20.00
1	FRONT BUMPER MOULDING CLIP (SN)	NOT NECESSARY	55.00	-
1	RADIATOR COOLANT 4L (SN)	NOT NECESSARY	130.00	-
			450.00	55.00

Report Ref No. CS/SMR22002157/Ety3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA.		1,600.00	400.00
	TO RUST PROOFING OF THE AFFECTED AREA.		170.00	30.00
	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.		350.00	30.00
	TO DIAGNOSTIC,CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE.	NOT NECESSARY	300.00	-
	TO READJUST AND REALIGN HEADLAMP AIM.		150.00	30.00
	TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT A/C CONDENSER,RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
	TO RESPRAY FRONT BUMPER.		250.00	200.00
	TO RESPRAY FRONT BUMPER CENTER UPPER MOULDING.	NOT NECESSARY	250.00	-
	TO RESPRAY FRONT BUMPER MOULDING.	NOT NECESSARY	250.00	-
	TO RESPRAY FRONT BUMPER LOWER MOULDING.	NOT NECESSARY	250.00	-
	TO RESPRAY FRONT FENDER PANEL.		250.00	200.00
			4,300.00	890.00
	GRAND TOTAL		11,150.64	3,562.04
	RECOMMENDED COST OF REPAIRS			3,562.04

Report Ref No. CS/SMR22002157/Ety3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.