



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7863K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	DISTORTED	581.40	581.40
1	REAR BUMPER SIDE RETAINER - RH (CONSISTENT)	BENT	131.35	131.35
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	351.40	351.40
1	REAR BUMPER REFLECTOR - RH (CONSISTENT)	CRACKED	181.90	68.50
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	129.00	50.00
	LESS 25% DISCOUNT		-343.76	-295.66
			1,031.29	886.99
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR WITH CONTROL UNIT (SN) (CONSISTENT)	SERVICEABLE	380.00	-
			380.00	-
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING SYSTEM.		100.00	20.00
	TO REMOVE & REFIX REVERSE SENSOR.		130.00	50.00
	TO REMOVE & REFIX INTERIOR UPHOLSTERY.	NOT NECESSARY	120.00	-
	TO RESPRAY AFFECTED AREAS.		800.00	400.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR REAR END PANEL, REAR FENDER RH & ALIGNED ALL PARTS.		750.00	300.00
			1,900.00	770.00
	<b>GRAND TOTAL</b>		<b>3,311.29</b>	<b>1,656.99</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,300.00</b>

Report Ref No. CS/ASM22002160/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.