

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002162/KYA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900016793
Claimant Vehicle No :	SND8812J	Insured Vehicle No :	SFM9966P
Date of Loss:	02/03/2022	Nature of Claim:	TP
		Claim No:	6280237162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND8812J		
Make & Model:	TESLA MODEL 3 PERFORMANCE, 2.0 E (A)	Engine No:	HIDDEN
Reg. Date:	12/11/2021 (Man. Year: 2021)	Chassis No:	LRW3F7EL4MC282975
Colour:	Metallic Pearl White	Odometer:	3282 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R20	Rear Tyre Size:	235/35 R20
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,354.67	1,786.16	1,568.51	46.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,310.00	1,630.00	55.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,294.67	3,096.16	3,198.51	50.81
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	08/03/2022	
Date Inspected:	08/03/2022 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	663.55 FL	*663.55 FL
2	1		*REAR BUMPER SIDE BRACKET RH	Distorted	7.48 FL	*7.48 FL
3	1		*REAR BOOTLID LAMP LH	Mtg Cracked	177.57 FL	*177.57 FL
4	1		*REAR BUMPER UNDER COVER	Serviceable	205.61 FL	*- FL
5	1		*REAR BUMPER REFLECTOR LH	Serviceable	20.56 FL	*- FL
6	2		*REAR BUMPER PARKING SENSOR	Shorted / Missing	317.76 FL	*317.76 FL
7	2		*REAR BUMPER PARKING SENSOR BRACKET	Necessary	9.34 FL	*9.34 FL
8	1		*REAR TAIL LAMP LH	Mtg Cracked	280.37 FL	*280.37 FL
9	1		*REAR TAIL LAMP BRACKET LH	Serviceable	2.80 FL	*- FL
10	1		*REAR TAIL LAMP REFLECTOR LH	Serviceable	36.45 FL	*- FL
11	1		*REAR FENDER LH	Repair	1,242.99 FL	*- FL
12	1		*REAR FENDER INNER SHIELD LH	Distorted	116.82 FL	*116.82 FL
13	1		*REAR FENDER INNER PANEL LH	Repair	112.15 FL	*- FL
14	1		*REAR AIR -DUCT	Dented	14.95 FL	*14.95 FL
15	1		*REAR REFLECTOR MOTOR	Mtg Cracked	252.34 FL	*252.34 FL
16	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
17	1		*REAR END PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
18	1		*REAR FENDER QUARTER GLASS SEALANT RH	Necessary	60.00 FS	*30.00 FS
19	1		*REAR FENDER INNER SHIELD CLIPS RH	Necessary	40.00 FS	*40.00 FS
					Sub Total (S\$)	3,700.74 1,970.18
					- List Item Discount on L Items 10.00/10.00% (S\$)	346.07 184.02
					Total Parts (S\$)	3,354.67 1,786.16

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE REFIX REPAIR & READJUST ACCIDENT AREA	New	1,200.00	700.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	1,000.00	500.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC	New	150.00	0.00
5	TO DAIGNOSIS FAULT CODE & RESET MEMORY	New	200.00	0.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	20.00
7	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	30.00
Gross Labour Cost (S\$)			2,940.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >