

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002172/DQY3M4**Date:** 17/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00047222105		
Claimant Vehicle No :	SMG4417P	Insured Vehicle No :	GBD8052C		
Date of Loss:	07/03/2022	Nature of Claim:	TP	Claim No:	SNM22D201590/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4417P		
Make & Model:	HONDA FIT, 1.5 (A)	Engine No:	L13B1444504
Reg. Date:	20/12/2018 (Man. Year: 2018)	Chassis No:	GK31337136
Colour:	White	Odometer:	35020 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,557.68	4,661.76	17,895.92	79.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,900.00	1,790.00	5,110.00	74.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,457.68	6,451.76	23,005.92	78.10
Approved Total (Overridden) (\$\$)		5,100.00		
(\$\$)	29,457.68	5,100.00	24,357.68	82.69
+ GST 7.00/7.00% (\$\$)	2,062.04	357.00	1,705.04	82.69
Nett Amount (\$\$)	31,519.72	5,457.00	26,062.72	82.69

INSPECTION

Date of Assignment:	08/03/2022	
Date Inspected:	09/03/2022 Inspected At:	C.S.ONG AUTO PTE LTD (HQ) 10, ANG MO KIO IND PARK 2A #02-16 AMK AUTO POINT SINGAPORE 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2022)
Parts:	144	HONDA FIT 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG4417P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Dented	1,680.00 FL	*712.00 FL
2	1		*BONNET INSULATOR	Not Necessary	405.00 FL	*- FL
3	2		*BONNET HINGE LH / RH @\$85.00 EACH	O/s Not Necessary / N/s Repair	170.00 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	290.50 FL	*- FL
5	1		*BONNET STRIKER LOCK	Not Necessary	49.00 FL	*- FL
6	1		*FRONT WIPER GARNISH	Serviceable	589.00 FL	*- FL
7	1		*A PILLAR LH	Not Necessary	1,495.00 FL	*- FL
8	1		*FRONT WINDSCREEN MOULDING	Not Necessary	321.40 FL	*- FL
9	1		*FRONT GRILLE	Cut	402.80 FL	*395.00 FL
10	1		*FRONT GRILLE BASE	Not Necessary	427.40 FL	*- FL
11	1		*FRONT GRILLE LOGO	Not Necessary	93.40 FL	*- FL
12	1		*FRONT GRILLE CHROME	Cut	398.00 FL	*292.30 FL
13	1		*HEAD LAMP LH / RH @\$1,595.00 EACH	O/s Not Necessary / N/s Broken	3,190.00 FL	*762.50 FL
14	1		*HEAD LAMP LOWER BRACKET LH / RH @\$95.00 EACH	O/s Not Necessary/ N/s Cracked	190.00 FL	*114.00 FL
15	1		*HEAD LAMP WIRE HARNESS COMPLETE	Not Necessary	1,420.00 FL	*- FL
16	1		*FRONT BUMPER	Cut	817.70 FL	*525.00 FL
17	1		*FRONT BUMPER SIDE RETAINER LH / RH @\$60.40 EACH	O/s Not Necessary / N/s Broken	120.80 FL	*28.00 FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	380.00 FL	*- FL
19	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	79.00 FL	*- FL
20	1		*FRONT BUMPER FOG LAMP GARNISH LH / RH @\$298.70 EACH	N/s Cut / O/s Not Necessary	597.40 FL	*39.20 FL
21	1		*FRONT BUMPER UNDERCOVER	Not Necessary	310.40 FL	*- FL
22	1		*FRONT BUMPER SPONGE	Not fitted	320.40 FL	*- FL
23	1		*FRONT REINFORCEMENT BAR	Bent	813.00 FL	*313.80 FL
24	1		*FRONT SUPPORT PANEL	Bent	1,420.00 FL	*512.00 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	125.40 FL	*- FL
26	1		*A/C CONDENSOR ASSY	Bent / Punctured	1,504.50 FL	*810.20 FL
27	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	275.00 FL	*- FL
28	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	278.00 FL	*- FL
29	1		*A/C CONDENSOR DISCHARGE PIPE	Not Necessary	310.00 FL	*- FL
30	1		*RADIATOR ASSY	Not Necessary	1,850.00 FL	*- FL
31	1		*RADIATOR FAN MOTOR	Not Necessary	436.00 FL	*- FL
32	1		*RADIATOR FAN BLADE	Not Necessary	278.00 FL	*- FL
33	1		*RADIATOR FAN COWLING	Not Necessary	325.00 FL	*- FL
34	1		*FRONT FENDER LH	Buckled / Torn	1,137.00 FL	*462.70 FL
35	1		*FRONT FENDER INNER PANEL LH	Repair	984.00 FL	*- FL
36	1		*FRONT FENDER INNER SHIELD LH	Deformed	303.00 FL	*108.80 FL
37	1		*FRONT FENDER QUARTER GLASS LH	Shattered	536.00 FL	*321.00 FL
38	1		*FRONT FENDER QUARTER GLASS MOULDING LH	Necessary	296.00 FL	*149.00 FL
39	1		*FRONT DOOR LH	Repair	1,678.00 FL	*- FL
40	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	109.00 FL	*- FL
41	1		*FRONT DOOR HINGE LH @\$128.00 EACH	Not Necessary	256.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT DOOR BLACK STICKER LH	Not Necessary	94.00 FL	*- FL
43	1		*FRONT FENDER BRACKET LH	Bent	317.00 FL	*169.20 FL
44	1		*FRONT WIPER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*A PILLAR SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*FRONT WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
48	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
50	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
51	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
52	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
53	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
54	1		*FRONT FENDER QUARTER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
55	1		*FRONT FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
56	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*15.00 FS
57	1		*COOLANT	Not Necessary	100.00 FS	*- FS
58	1		*FRONT NO. PLATE & CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 27,972.10 5,804.70
- List Item Discount on L Items 20.00/20.00% (S\$) 5,414.42 1,142.94

Total Parts (S\$) 22,557.68 4,661.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	800.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	800.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
4	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	80.00
5	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	0.00
7	TO RNR FRONT FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	40.00
8	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	New	400.00	0.00
9	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,900.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >