



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 5118P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAIL LAMP RH	BROKEN	700.00	542.00
1	TAILGATE EMBLEM	NECESSARY	50.00	50.00
1	TAILGATE "SUZUKI" LOGO	NECESSARY	52.00	52.00
1	TAILGATE "SWIFT" LOGO	NECESSARY	52.00	52.00
1	REAR BUMPER	DENTED	800.00	550.00
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	25.00	-
10	REAR BUMPER CLIP @\$5.50	NECESSARY	55.00	30.00
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 15% DISCOUNT		-260.10	-191.40
			1,473.90	1,084.60
	<b><u>LABOUR</u></b>			
	TO REPAIR & STRAIGHTEN REAR END PANEL AND TAILGATE. TO REMOVE & REPLACE DAMAGED PARTS AND REALIGN ALL CONNECTION. INCLUSIVE OF THE REPAIR OF TAILGATE.		500.00	200.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.		600.00	400.00
			1,100.00	600.00
	<b>GRAND TOTAL</b>		<b>2,573.90</b>	<b>1,684.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,350.00</b>

Report Ref No. CS/SMR22002174/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.