

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002177/BVY3N2**Date:** 05/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00063932101

**Claimant Vehicle
No :** SLV9419J**Insured Vehicle
No :** GBD8297M

Date of Loss: 01/03/2022

Nature of Claim: TP

Claim
No: SNM22D201494/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLV9419J**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 2ZR0A43009

Reg. Date: 24/01/2018 (Man. Year: 2017)

Chassis No: JTDGG20W80J008545

Colour: Grey

Odometer: 74426 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,680.32	7,064.69	6,615.63	48.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	2,300.00	2,450.00	51.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,430.32	9,364.69	9,065.63	49.19
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	18,430.32	7,500.00	10,930.32	59.31
+ GST 7.00/7.00% (S\$)	1,290.12	525.00	765.12	59.31
Nett Amount (S\$)	19,720.44	8,025.00	11,695.44	59.31

INSPECTION

Date of Assignment: 08/03/2022

Date Inspected: 09/03/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV9419J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,626.10 FL	*1,466.25 FL
2	1		*REAR TAILGATE LOCK ASSEMBLY	Jammed	412.70 FL	*374.40 FL
3	1		*REAR TAILGATE WEATHERSTRIP	Not Damaged	334.50 FL	*- FL
4	1		*REAR TAILGATE LOGO	Necessary	72.20 FL	*66.20 FL
5	1		*REAR TAILGATE VALVE MATIC EMBLEM	Necessary	45.80 FL	*45.80 FL
6	1		*REAR TAILGATE ELEGANCE EMBLEM	Necessary	49.80 FL	*49.80 FL
7	1		*REAR TAILGATE LOCK STRIKER	Not Damaged	37.30 FL	*- FL
8	1		*REAR TAILGATE REFLECTOR LAMP RH	Cut	460.35 FL	*415.60 FL
9	1		*REAR TAILGATE REFLECTOR LAMP LH	Cut	460.35 FL	*415.60 FL
10	1		*REAR TAILGATE OUTER CHROME GARNISH	Broken	287.50 FL	*150.20 FL
11	1		*REAR TAILGATE HINGE RH	Not Damaged	68.70 FL	*- FL
12	1		*REAR TAILGATE HINGE LH	Not Damaged	68.70 FL	*- FL
13	1		*REAR TAILGATE DAMPER RH	Bent	173.20 FL	*173.20 FL
14	1		*REAR TAILGATE DAMPER LH	Bent	173.20 FL	*173.20 FL
15	1		*REAR TAILGATE GLASS MOULDING	Necessary	187.90 FL	*110.00 FL
16	1		*REAR TAILGATE INNER TRIM BOARD	Broken	581.30 FL	*345.20 FL
17	1		*REAR TAILGATE WIPER MOTOR	Not Damaged	529.30 FL	*- FL
18	1		*REAR BUMPER	Broken	611.80 FL	*543.90 FL
19	1		*REAR BUMPER SIDE RETAINER RH	Necessary	97.40 FL	*89.90 FL
20	1		*REAR BUMPER SIDE RETAINER LH	Necessary	97.40 FL	*89.90 FL
21	1		*REAR BUMPER BRACKET RH	Broken	53.80 FL	*53.80 FL
22	1		*REAR BUMPER BRACKET LH	Broken	53.80 FL	*53.80 FL
23	1		*REAR BUMPER REFLECTOR RH	Broken	62.00 FL	*56.00 FL
24	1		*REAR BUMPER REFLECTOR LH	Broken	62.00 FL	*56.00 FL
25	1		*REAR BUMPER DAMPER RH	No such part	140.65 FL	*- FL
26	1		*REAR BUMPER DAMPER LH	No such part	140.65 FL	*- FL
27	1		*KEYLESS ENTRY ANTENNA	Broken	192.20 FL	*138.50 FL
28	1		*REAR END PANEL	Dented	683.70 FL	*540.80 FL
29	1		*REAR END PANEL TOP GARNISH	Broken	298.00 FL	*253.00 FL
30	1		*REAR EXHAUST PIPE ASSEMBLY	Not Damaged	1,039.10 FL	*- FL
31	2		*REAR EXHAUST PIPE MOUNTING	Not Damaged	96.60 FL	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Not Damaged	349.00 FL	*- FL
33	1		*REAR SPARE TYRE BRACKET	Not Damaged	407.50 FL	*- FL
34	1		*REAR TAILLAMP ASSEMBLY RH	Broken	652.50 FL	*411.70 FL
35	1		*REAR TAILLAMP ASSEMBLY LH	Broken	652.50 FL	*411.70 FL
36	1		*REAR FENDER INNER TRIM BOARD RH	Broken	765.30 FL	*480.10 FL
37	1		*REAR FENDER INNER TRIM BOARD LH	Broken	765.30 FL	*480.10 FL
38	1		*REAR FLOOR PANEL	Not Damaged	1,025.30 FL	*- FL
39	1		*REAR FLOOR PANEL TOP SIDE BOARD RH	Not Damaged	159.00 FL	*- FL
40	1		*REAR FLOOR PANEL TOP SIDE BOARD LH	Not Damaged	159.00 FL	*- FL
41	1		*REAR FLOOR PANEL TOP BOARD REAR GARNISH	Not Damaged	398.00 FL	*- FL
42	1		*REAR FLOOR PANEL TOP BOARD	Not Damaged	580.70 FL	*- FL
43	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
44	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	120.00 FS	*30.00 FS
45	1		*SET REAR TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
46	1		*REAR TAILGATE CAMERA	Short Circuit	500.00 FS	*300.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
48	1		*SET REAR TAILLAMP CLIPS	Necessary	50.00 FS	*20.00 FS
49	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
50	1		*REAR BUMPER REVERSE SENSOR	Short Circuit	250.00 FS	*200.00 FS
51	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
52	1		*REAR TAILGATE SEALANT	Necessary	150.00 FS	*30.00 FS
53	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
54	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
55	1		*REAR FENDER LH	Dented	1,035.00 FL	*921.60 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					17,717.10	9,156.25
- List Item Discount on L Items 25.00/25.00% (S\$)					4,036.78	2,091.56
Total Parts (S\$)					13,680.32	7,064.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,REMOVE & REFIX PARTS	New	1,600.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	800.00
3	WIRING & BULB CHECK	New	80.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	80.00
5	TO REMOVE & REFIX REAR TAILGATE CAMERA	New	150.00	40.00
6	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	60.00
7	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT,PROGRAMMING & CALIBRATION	New	480.00	0.00
8	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	0.00
9	TO REMOVE & REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
10	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
11	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	120.00
12	TO REMOVE & REFIX REAR EXHAUST PIPE	New	120.00	0.00
Gross Labour Cost (\$\$)			4,750.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >