

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002179/EQY3N2**Date:** 29/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00143582000

**Claimant Vehicle No :** SMZ676J **Insured Vehicle No :** SJY5085Y

Date of Loss: 07/03/2022 Nature of Claim: TP Claim No: SNM22D201592/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMZ676J**

Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FGKU115031

Reg. Date: 10/04/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU883320

Colour: White Odometer: 22042 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,221.80	5,249.60	4,972.20	48.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,920.00	490.00	20.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,631.80</b>	<b>7,169.60</b>	<b>5,462.20</b>	<b>43.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,750.00</b>		
<b>(S\$)</b>	12,631.80	5,750.00	6,881.80	54.48
<b>+ GST 7.00/7.00% (S\$)</b>	884.23	402.50	481.73	54.48
<b>Nett Amount (S\$)</b>	<b>13,516.03</b>	<b>6,152.50</b>	<b>7,363.53</b>	<b>54.48</b>

**INSPECTION**

Date of Assignment: 08/03/2022

Date Inspected: 09/03/2022 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)  
38 Toh Guan Road East, #01-57, Enterprise Hub  
Singapore 608581

Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2022)
<b>Parts:</b>	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMZ676J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	500.00 F	*- FL
2	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	40.00 F	*- FL
3	1		*CENTER GRILLE WITH LOGO BADGE	Broken	550.00 F	*550.00 FL
4	1		*HEADLAMP RH	Cut	1,199.00 F	*1,199.00 FL
5	1		*REAR BUMPER	Broken	500.00 F	*500.00 FL
6	2		*REAR BUMPER SIDE RETAINER LH/RH	Broken	60.00 F	*60.00 FL
7	1		*REAR BUMPER LOWER GARNISH	Broken	355.00 F	*355.00 FL
8	1		*BOOT LID	Dented	1,783.00 F	*1,783.00 FL
9	1		*BOOT LID LOCK	Bent	120.00 F	*120.00 FL
10	2		*BOOT LID BOTH HINGE LH/RH	Not Necessary	120.00 F	*- FL
11	1		*BOOT LID LOGO BADGE	Necessary	200.00 F	*60.00 FL
12	1		*BOOT LID EMBLEM AVANTE	Necessary	35.00 F	*35.00 FL
13	1		*REAR BUMPER REFLECTOR LAMP RH	Not Necessary	202.00 F	*- FL
14	1		*REAR REINFORCEMENT	Broken	295.00 F	*295.00 FL
15	1		*END PANEL	Dented	455.00 F	*455.00 FL
16	1		*CAR PLATE BASE GARNISH	Broken	25.00 F	*25.00 FL
17	1		*HEADLAMP RH	Not Necessary	1,199.00 F	*- FL
18	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
19	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
20	1		*CENTER GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
21	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
22	1		*REAR BUMPER LOWER SKIRT WITH DIFFUSER	Cut	900.00 FS	*300.00 FS
23	1		*FRONT CAR PLATE WITH HOLDER	Broken	35.00 FS	*35.00 FS
24	1		*REAR CAR PLATE WITH HOLDER	Broken	35.00 FS	*35.00 FS
25	1		*END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
26	1		*FRONT BUMPER STICKER	Necessary	100.00 FS	*80.00 FS
27	1		*REAR BUMPER STICKER	Necessary	300.00 FS	*80.00 FS
28	2		*CAR PLATE STICKER FRONT/REAR	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,458.00</b>	<b>6,337.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	1,087.40
<b>+ Margin on L,N Items 10.00/0.00% (\$\$)</b>	763.80	0.00
<b>Total Parts (\$\$)</b>	<b>10,221.80</b>	<b>5,249.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	1,000.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	800.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
4	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	30.00
5	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	60.00	30.00
6	TO REPLACE AND FOCUS HEADLAMP RH	New	30.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>2,410.00</b>	<b>1,920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >