



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21010756/Ety3e2-1 Date: 05/04/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 1017B	Veh. Inspected	XD 2272M	
Policy No.	Z21VC5008557	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/025059	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	08/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO	c.c	12882	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	FP51JDA00602	Colour	WHITE	
Odometer	54582 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
R/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/10/2021	Inspection Date	20/10/2021	
Survey held at	245 JALAN AHMAD IBRAHIM			
Repairer	LYS ENGINEERING			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	