

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 301S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	CUT	3,923.30	2,944.10
1	FRT BUMPER PARK SENSOR RH	SHORT CIRCUIT	236.50	236.50
1	FRT FENDER RH	CUT	1,455.70	1,455.70
1	FRT FENDER COWLING RH	NOT DAMAGED	250.30	-
1	FRT FENDER AIR VENT MOULDING RH	NOT DAMAGED	138.60	-
1	FRT FENDER SIGNAL LAMP RH	NOT DAMAGED	182.40	-
1	FRT ALLOY RIM RH (DENTED / DEFACED)	NOT CONSISTENT WITH THE IMPACT	1,820.30	-
1	FRT KNUCKLE ARM RH	NOT DAMAGED	1,329.70	-
1	FRT LOWER ARM RH	NOT DAMAGED	1,209.00	-
1	RH SIDE MIRROR ASSY	TO REPAIR SEE LABOUR	1,021.20	-
1	FRT DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-1,156.70	-463.63
			10,410.30	4,172.67
	LABOUR			
	TO REMOVE AND REINSTALL AFFECTED ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS.TO CHECK ELECTRICAL SYSTEM AND CALIBRATE/FOCUS HEADLAMP.	NOT NECESSARY	70.00	-
	TO REMOVE,CHECK AND REPLACE RHF UNDERCARRIAGE PARTS.		150.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		60.00	60.00
	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF RH SIDE MIRROR ASSY AND FRT DOOR RH.		1,000.00	400.00
	TO SPRAY PAINTING,BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	600.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	NOT NECESSARY	60.00	-
			2,340.00	1,180.00
	GRAND TOTAL		12,750.30	5,352.67

Report Ref No. CS3/CTI21009488/Bvy3n2-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	4,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/CTI21009488/Bvy3n2-1



**Automotive Assessor** 



**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**