

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG122002186/UVY3N2**Date:** 18/03/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBJ8579T**Insured Vehicle No :** PB2800U

Date of Loss: 09/02/2022

Nature of Claim:

TP

Claim No: CDMFG22000362

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ8579T**

Make &amp; Model: MITSUBISHI L200, 2.4 D DOUBLE CAB (M)

Engine No: 4N15UDR8486

Reg. Date: 18/09/2019 (Man. Year: 2019)

Chassis No: MMCJYKL10KH014714

Colour: Silver

Odometer: 156895 km

Engine Capacity: 2442 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/70R16

Rear Tyre Size: 245/70R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	897.80	613.80	284.00	31.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	80.00	120.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,097.80</b>	<b>693.80</b>	<b>404.00</b>	<b>36.80</b>

INSPECTION

Date of Assignment: 08/03/2022

Date Inspected: 09/03/2022 Inspected At:

Kai Liang Motor Service - Kaki Bukit (HQ)

BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY

Singapore 417883

Estimated Period of Repair: 0.5 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Mar 2022)	
Parts:	N/A	MITSUBISHI L200 2.4 D DOUBLE CAB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ8579T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT SIDE MIRROR ASSEMBLY	Cracked	897.80 F	*682.00 FN
						F=Franchise part. N=NettItemDisc.
					Sub Total (S\$)	897.80 682.00
					- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00 68.20
					Total Parts (S\$)	897.80 613.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND CHANGE SIDE MIRROR	New	200.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>200.00</b>	<b>80.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >