

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22002188/AVCE2

**Date:** 26/05/2022

### REFERENCE

Insured/Claimant:	TAN KUAN TIAN	Policy No:	1800073006		
Date of Loss:	03/03/2022	Nature of Claim:	OD	Claim No:	9545546289SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC900H		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK058920
Reg. Date:	05/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF41JA148372
Colour:	Grey	Odometer:	68510 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,488.00	8,879.76	10,608.24	54.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,814.00	3,572.00	6,242.00	63.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>29,302.00</b>	<b>12,451.76</b>	<b>16,850.24</b>	<b>57.51</b>
<b>- Excess (S\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>28,202.00</b>	<b>11,351.76</b>	<b>16,850.24</b>	<b>59.75</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,974.14</b>	<b>794.62</b>	<b>1,179.52</b>	<b>59.75</b>
<b>Nett Amount (S\$)</b>	<b>30,176.14</b>	<b>12,146.38</b>	<b>18,029.76</b>	<b>59.75</b>

### INSPECTION

Date of Assignment:	09/03/2022		
Date Inspected:	08/03/2022	Inspected At:	24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	629.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Damaged	79.00 FS	*63.20 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	218.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,478.00 FS	*- FS
8	1		*RADIATOR AIR GUIDE GRILLE - RH	Not Necessary	151.00 FS	*- FS
9	1		*RADIATOR GUIDE SECTION - RH	Cracked	41.00 FS	*32.24 FS
10	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
11	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
12	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
13	1		*HORN - RH	Not Necessary	139.00 FS	*- FS
14	1		*HORN SUPPORT - RH	Not Necessary	33.00 FS	*- FS
15	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	488.00 FS	*- FS
16	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
17	1		*FRONT FENDER - RH	Dented	861.00 FS	*688.80 FS
18	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
19	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	81.00 FS	*64.24 FS
20	1		*FRONT FENDER BRACKET - RH	Not Necessary	41.00 FS	*- FS
21	1		*FRONT FENDER BRACKET CENTER - RH	Not Necessary	55.00 FS	*- FS
22	1		*POP ROVET (6PCS)	Necessary	23.00 FS	*18.24 FS
23	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
24	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	262.00 FS	*209.60 FS
25	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	219.00 FS	*- FS
26	1		*FRONT WHEEL SPOILER	Torn	82.00 FS	*65.12 FS
27	1		*FRONT WHEEL SPOILER LOWER - RH	Not Necessary	40.00 FS	*- FS
28	1		*FRONT FENDER LEDGE COVER SHORT - RH	Deformed	26.00 FS	*20.16 FS
29	1		*HEADLIGHT - RH	Cracked	7,693.00 FS	*6,154.40 FS
30	1		*HEADLIGHT POWER MODULE	Not Necessary	840.00 FS	*- FS
31	1		*HEADLIGHT CONTROL UNIT	Not Necessary	840.00 FS	*- FS
32	1		*HEADLIGHT HOSE - RH	Not Necessary	42.00 FS	*- FS
33	1		*SPACER (3PCS)	Not Necessary	136.00 FS	*- FS
34	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
35	1		*LOCK CARRIER SUPPORT - RH	Not Necessary	43.00 FS	*- FS
36	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE - RH OUTER	Not Necessary	32.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE - RH INNER	Not Necessary	14.00 FS	*- FS
39	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
40	1		*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
41	1		*LIFT CYLINDER BRACKET - RH	Not Necessary	7.00 FS	*- FS
42	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
43	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
44	1		*SUNDRIES	Necessary	400.00 FS	*28.96 FS
45	1		*FRONT FENDER LEDGE COVER LONG - RH	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **19,488.00** **8,879.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER	New	3,000.00	1,650.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,814.00</b>	<b>3,572.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >