

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002189/ATCE2

Date: 24/06/2022

REFERENCE

Insured/Claimant: MOHAMMAD FAIZAL DE SILVA Policy No: 1900115802-02
Date of Loss: 26/02/2022 Nature of Claim: OD Claim No: 0470009998SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM6742E**
Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZC25993
Reg. Date: 09/07/2019 (Man. Year: 2018) Chassis No: WAUZZZ8V7K1012853
Colour: Black Odometer: 30770 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$103,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,474.00	2,624.80	3,849.20	59.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,432.00	752.00	2,680.00	78.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,906.00	3,376.80	6,529.20	65.91
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	9,306.00	2,776.80	6,529.20	70.16
+ GST 7.00/7.00% (S\$)	651.42	194.38	457.04	70.16
Nett Amount (S\$)	9,957.42	2,971.18	6,986.24	70.16

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 08/03/2022 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*ALUMINIUM RIM	Cut	2,606.00 FS	*2,084.80 FS
2	1		*TRACK CONTROL ARM	Not Necessary	393.00 FS	*- FS
3	1		*REAR AXLE BEAM	Not Necessary	2,250.00 FS	*- FS
4	1		*GAS SHOCK ABSORBER	Not Necessary	270.00 FS	*- FS
5	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
6	1		*RHS FRONT TYRE	Punctured	270.00 FS	*270.00 FS
7	1		*RHS REAR TYRE	Punctured	270.00 FS	*270.00 FS
8	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,474.00	2,624.80
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW LHS FRONT WHEEL LOWER ARM	New	280.00	0.00
2	TO REMOVE AND REINSTALL REAR WHEEL SUSPENSION ASSY TO FACILITATE RENEWAL OF REAR SUBFRAME	New	2,400.00	0.00
3	TO REMOVE AND RENEW RHS FRONT RIM WITH TYRE AND RHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	560.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			3,432.00	752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >