

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002191/AQCE2**Date:** 04/10/2022**REFERENCE**

Insured/Claimant:	SADAT QAYYUM	Policy No:	7210054291	
Date of Loss:	04/03/2022	Nature of Claim:	OD	Claim No: 8731993742SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA7786Z		
Make & Model:	AUDI A6, 2.0 TFSI (A)	Engine No:	DKY015489
Reg. Date:	31/05/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF24MN071864
Colour:	Blue	Odometer:	4438 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$228,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,195.00	15,301.20	14,893.80	49.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	27,812.00	11,472.00	16,340.00	58.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	58,007.00	26,773.20	31,233.80	53.84
- Excess (\$\$)	250.00	250.00	0.00	0.00
(\$\$)	57,757.00	26,523.20	31,233.80	54.08
+ GST 7.00/7.00% (\$\$)	4,042.99	1,856.62	2,186.37	54.08
Nett Amount (\$\$)	61,799.99	28,379.82	33,420.17	54.08

INSPECTION

Date of Assignment:	09/03/2022	
Date Inspected:	08/03/2022	Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair:	14.0 days	Repairer: Premium Automobiles Pte Ltd

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*B-PILLAR FRAME-LH	Dented	4,506.00 FS	*3,604.80 FS
2	1		*REAR WINDSCREEN	Not Necessary	1,307.00 FS	*- FS
3	2		*QUARTER WINDOW STRIP-LH/RH	Not Necessary	7.00 FS	*- FS
4	1		*QUARTER WINDOW-LH	Not Necessary	788.00 FS	*- FS
5	2		*PRIMER	Not Necessary	44.00 FS	*- FS
6	1		*SILL TRIM STRIP-LH REAR	Necessary	133.00 FS	*106.00 FS
7	1		*SILL TRIM STRIP-LH FRONT	Necessary	209.00 FS	*166.80 FS
8	1		*B-PILLAR TRIM-LH	Deformed	960.00 FS	*768.00 FS
9	1		*B-PILLAR ATTACHMENT PARTS	Necessary	136.00 FS	*108.80 FS
10	1		*B-PILLAR ADHESIVE TAPES	Necessary	64.00 FS	*51.12 FS
11	1		*REAR BUMPER	Repair	3,012.00 FS	*- FS
12	1		*REAR BUMPER FIXING PARTS	Not Necessary	246.00 FS	*- FS
13	1		*REAR BUMPER GUIDE SECTION-LH LOWER	Not Necessary	71.00 FS	*- FS
14	1		*REAR DOOR-LH	Distorted	4,489.00 FS	*3,591.20 FS
15	1		*REAR DOOR OUTER SEAL-LH	Necessary	191.00 FS	*152.80 FS
16	1		*REAR DOOR SEAL-LH	Not Necessary	206.00 FS	*- FS
17	1		*REAR DOOR CATCH-LH	Not Necessary	0.00 FS	*- FS
18	1		(NPA) *REAR DOOR HINGE-LH LOWER	Not Necessary	0.00 FS	*- FS
19	1		(NPA)			
20	1		*REAR DOOR HANDLE-LH	Not Necessary	389.00 FS	*- FS
21	1		*REAR DOOR HANDLE PLATE-LH	Not Necessary	109.00 FS	*- FS
22	1		*REAR DOOR HANDLE PANEL UPPER PART CAP-LH	Not Necessary	100.00 FS	*- FS
23	1		*FRONT DOOR-LH	Distorted	4,489.00 FS	*3,591.20 FS
24	1		*FRONT DOOR OUTER SEAL-LH	Necessary	191.00 FS	*152.80 FS
25	1		*FRONT DOOR CATCH-LH	Not Necessary	0.00 FS	*- FS
26	1		(NPA)			
27	1		*FRONT DOOR COVER-LH	Not Necessary	121.00 FS	*- FS
28	1		*FRONT DOOR HANDLE-LH	Cut	389.00 FS	*310.80 FS
29	1		*FRONT DOOR HANDLE TRIM HANDLE-LH	Cut	109.00 FS	*86.80 FS
30	1		*FRONT DOOR PANEL UPPER PART CAP-LH	Not Necessary	100.00 FS	*- FS
31	1		*FRONT DOOR HANDLE SENSOR-LH	Not Necessary	278.00 FS	*- FS
32	1		*FRONT DOOR SLIDE VALVE-LH	Not Necessary	15.00 FS	*- FS
33	1		*FRONT DOOR HANDLE UNDERTRAY-LH	Necessary	6.00 FS	*4.40 FS
34	1		*FRONT DOOR HANDLE UNDERTRAY OUTER-LH	Necessary	7.00 FS	*5.36 FS
35	1		*FRONT DOOR HANDLE MOUNTING BAR-LH	Not Necessary	0.00 FS	*- FS
36	1		(NPA)			
37	1		*WING MIRROR MOUNTING-LH	Not Necessary	3,069.00 FS	*- FS
38	1		*FRONT DOOR WINDOW REGULATOR-LH	Damaged	385.00 FS	*308.00 FS
39	1		*FRONT DOOR WINDOW MOTOR-LH	Not Necessary	376.00 FS	*- FS
40	1		*FRONT DOOR WINDOW SLOT SILL TRIM STRIP-LH OUTER	Not Necessary	224.00 FS	*- FS
41	1		*PICTOGRAM STICKER	Necessary	27.00 FS	*21.28 FS
42	1		*REAR ALUMINIUM RIM	Cut	1,847.00 FS	*1,477.60 FS
43	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
44	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
45	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
46	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
47	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
48	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
49	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
50	1		*SUNDRIES	Necessary	500.00 FS	*13.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 30,195.00 15,301.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER	New	600.00	0.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST	New	200.00	0.00
5	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	800.00	560.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
7	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
8	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY,LHS B-PILLAR LOWER TRIMS.TO DISLODGE AND REINSTALL CARPET TO FACILITATE THE RENEWAL FOR LHS B-PILLAR AND LHS SILL PANEL	New	980.00	980.00
9	TO DISMANTLE AND RENEW REAR BUMPER,LHS SILL PANEL TRIM,LHS REAR DOOR AND LHS FRONT DOOR.TO CUT OUT AND WELD LHS REAR FENDER,LHS SILL PANEL AND LHS B-PILLAR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	11,200.00	4,500.00
10	TO RESPRAY REAR BUMPER,LHS REAR FENDER,LHS REAR DOOR,LHS FRONT DOOR,DOOR HANDLES,LHS WING MIRROR COVER,LHS SILL PANEL TRIM,LHS B-PILLAR,LHS SILL PANEL,ROOF CHANNEL,DRAIN CHANNEL,DOOR ENTRANCE REAR END PANELLING	New	10,000.00	4,600.00
11	TO RENEW LHS REAR RIM AND CARRY OUT ALIGNMENT TEST	New	280.00	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			27,812.00	11,472.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >