

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22002200/Tty3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	15/03/2022	
	ATTN: OH VALE			Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SML 5420X	Veh. Inspected	l	SLL 102J
	Policy No.	P2292098	Coverage (\$)		0.00
	Claim No.	S2M03V6Z	Excess (\$)		0.00
	Assign From	OH VALE	Assign Date		09/03/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA ODYSSEY	c.c		2356
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	JHMRC1880GC206781	Colour		BLACK
	Odometer	551536 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/55 R17	ROADBOSS		6 mm
	L/H Front Tyre	225/55 R17	ROADBOSS		6 mm
	R/H Rear Tyre	225/55 R17	ROADBOSS		6 mm
	L/H Rear Tyre	225/55 R17	ROADBOSS		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
5.	General Information				
	Accident Date	08/03/2022	Inspect Date /	Time	09/03/2022 (02:00 PM)
	Survey held at SPEEDWERKZ PTE LTD				
	13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,500				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

Report Ref No. CS3/ASM22002200/Tty3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser