

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd  
11 Keppel Road, #11-01 ABI Plaza  
Singapore 089057

**Our File No:** CS/HLA22002201/EQY3M4

**Date:** 06/07/2022

### REFERENCE

Insured/Claimant:	LIU JIANLIN	Policy No:	MP314086	
Date of Loss:	05/03/2022	Nature of Claim:	OD	Claim No: MPC03221

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS4916C	Engine No:	34135031B38A15A
Make & Model:	MINI COOPER, 1.5 5DR FWD LED ABS (A)	Chassis No:	WMWXS520202F23995
Reg. Date:	21/08/2017 (Man. Year: 2017)	Odometer:	13451 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/45 R17	Rear Tyre Size:	205/45 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,839.70	6,031.20	808.50	11.82
Miscellaneous Items	90.00	90.00	0.00	0.00
Labour	1,740.00	1,510.00	230.00	13.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,669.70</b>	<b>7,631.20</b>	<b>1,038.50</b>	<b>11.98</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>- Excess (S\$)</b>	0.00	750.00	-750.00	
<b>(S\$)</b>	8,669.70	5,250.00	3,419.70	39.44
<b>+ GST 7.00/7.00% (S\$)</b>	606.89	367.50	239.39	39.45
<b>Nett Amount (S\$)</b>	<b>9,276.59</b>	<b>5,617.50</b>	<b>3,659.09</b>	<b>39.44</b>

### INSPECTION

Date of Assignment:	09/03/2022	Present Location:	Wah Hong Motors & Credit Pte Ltd (HQ)
Date Inspected:	09/03/2022	Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ)
			38 Toh Guan Road East, #01-57, Enterprise Hub
			Singapore 608581
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 06 Jul 2022)

**Parts:** 144      MINI COOPER 1.5 5DR FWD LED ABS (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMS4916C)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Bonnet</b> (WCP)	Dented	1,180.00 F	*1,180.00 F
2	1		<b>*Headlamp LH</b> (WCP)	Broken	800.00 F	*800.00 F
3	1		<b>*Headlamp outer chrome LH</b> (WCP)	Missing	70.00 F	*70.00 F
4	1		<b>*Front bumper</b> (WCP)	Broken	680.00 F	*680.00 F
5	1		<b>*Front bumper side bracket LH</b> (WCP)	Broken	65.00 F	*65.00 F
6	1		<b>*Front fender shield LH</b> (WCP)	Crushed	318.00 F	*318.00 F
7	1		<b>*Front wheel arch garnish LH</b> (WCP)	Cut	130.00 F	*130.00 F
8	1		<b>*Front wheel arch garnish sensor LH</b> (WCP)	Not Necessary	170.00 F	*- F
9	1		<b>*Front reverse sensor wire harness</b> (WCP)	Not Necessary	430.00 F	*- F
10	1		<b>*Bonnet sticker LH/RH @2*\$138</b> (WCP)	Necessary	276.00 F	*276.00 F
11	1		<b>*Front bumper lower garnish</b> (WCP)	Broken	190.00 F	*190.00 F
12	1		<b>*Front bumper lower garnish sensor LH</b> (WCP)	Not Necessary	170.00 F	*- F
13	1		<b>*Front rim 17inch</b> (WCP)	Cut	900.00 F	*900.00 F
<b><u>Supplementary #1</u></b>						
14	1		<b>*FRONT FENDER LH</b> (WCP)	Dented	450.00 F	*450.00 F
15	1		<b>*FRONT FENDER LAMP TRIM GARNISH LH</b> (WCP)	Necessary	180.00 F	*180.00 F
16	1		<b>*FRONT BUMPER SPONGE</b> (WCP)	Broken	60.00 F	*60.00 F
17	1		<b>*HEADLAMP LOWER BRACKET PANEL LH</b> (WCP)	Dented	80.00 F	*80.00 F
18	1		<b>*BONNET LOOG BADGE WITH ADHERSIVE</b> (WCP)	Necessary	75.00 F	*75.00 F
<b><u>Supplementary #2</u></b>						
19	1		<b>*Front lower arm LH</b> (WCP)	Bent	170.00 F	*170.00 F
20	1		<b>*Front lower arm bushing with bracket LH</b> (WCP)	Bent	120.00 F	*120.00 F

F=Franchise part.

<b>Sub Total (\$)</b>	<b>6,514.00</b>	<b>5,744.00</b>
<b>+ Margin on L,N Items 5.00/5.00% (\$)</b>	325.70	287.20
<b>Total Parts (\$)</b>	<b>6,839.70</b>	<b>6,031.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b><u>Miscellaneous Items</u></b>				
1	1	<b>Bonnet insulator clips</b> (NECESSARY)	30.00	30.00
2	1	<b>Front Bumper clips</b> (NECESSARY)	35.00	35.00
3	1	<b>Front fender shield clips</b> (NECESSARY)	25.00	25.00
<b>Sub Total (S\$)</b>			<b>90.00</b>	<b>90.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and component	New	800.00	600.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	600.00	600.00
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00	50.00
4	To remove and replace front tyre rim LH and wheel balancing	New	50.00	30.00
5	To check and adjust wheel Computerize alignment	New	80.00	80.00
<b><u>Supplementary #2</u></b>				
<b><u>Labour Items</u></b>				
6	To carried out remove and replace front undercarriage LH	New	150.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>1,740.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >