

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22002205/AEA3Q2**Date:** 29/08/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100455992
Claimant Vehicle No :	SKE6700S	Insured Vehicle No :	SKA4680A
Date of Loss:	08/03/2022	Nature of Claim:	TP
		Claim No:	7692880192SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE6700S	Engine No:	CJT047697
Make & Model:	AUDI Q7, 3.0 (A)	Chassis No:	WAUZZZ4L8CD017919
Reg. Date:	11/01/2012 (Man. Year: 2011)	Odometer:	212859 km
Colour:	Brown		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/45R20	Rear Tyre Size:	275/45R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	112,637.00	58,965.00	53,672.00	47.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	45,374.00	26,944.00	18,430.00	40.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	158,011.00	85,909.00	72,102.00	45.63
Approved Total (Overridden) (S\$)		62,597.00		
Nett Amount (S\$)	158,011.00	62,597.00	95,414.00	60.38
+ Loss of Use (17.0 x S\$120.00/day) (S\$)		2,040.00		
+ Medical Costs (S\$)		238.25		
Nett Liability (S\$)		64,875.25		

INSPECTION

Date of Assignment:	10/03/2022		
Date Inspected:	10/03/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	0.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE: \$121,000.00

LTA REIMBURSEMENT VALUE (RV): \$58,403.00

NETT VALUE: \$62,597.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	3,767.00 FS	*3,767.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	259.00 FS	*259.00 FS
3	1		*FRONT BUMPER GRILLE LOWER CENTRE	Cracked	265.00 FS	*265.00 FS
4	1		*NOISE INSULATION	Missing	512.00 FS	*512.00 FS
5	1		*FRONT BUMPER COVER -LH/RH	N/S Missing	156.00 FS	*78.00 FS
6	1		*FRONT BUMPER SPOILER -LH/RH	N/S Missing	126.00 FS	*63.00 FS
7	1		*RADIATOR GRILLE	Cracked	1,804.00 FS	*1,804.00 FS
8	1		*FOAM FILLER PIECE	Cracked	192.00 FS	*192.00 FS
9	1		*FRONT REINFORCEMENT BEAM	Bent	927.00 FS	*927.00 FS
10	2		*FRONT BUMPER HOLDER -LH/RH	Distorted	846.00 FS	*846.00 FS
11	2		*FRONT BUMPER SUPPORT -LH/RH	Distorted	106.00 FS	*106.00 FS
12	2		*FRONT BUMPER GUIDE PIECE LH/RH	Distorted	158.00 FS	*158.00 FS
13	1		*FRONT BUMPER COVER -UPPER	Missing	167.00 FS	*167.00 FS
14	1		*STICKER FOR AIR CONDITIONER	Necessary	34.00 FS	*34.00 FS
15	1		*FRONT SENSOR -LH/RH (NPA)	N/S Damaged	0.00 FS	*- FS
16	1		*FRONT SENSOR -LH/RH CENTRE (NPA)	N/S Damaged	0.00 FS	*- FS
17	1		*FRONT BUMPER WIRING	*Check	750.00 FS	*- FS
18	1		*HORN BRACKET	Bent	54.00 FS	*54.00 FS
19	1		*FRONT HORN -LOW TONE	Not Necessary	154.00 FS	*- FS
20	1		*FRONT HORN -HIGH TONE	Not Necessary	240.00 FS	*- FS
21	2		*FRONT FENDER -LH/RH	N/S Distorted / O/S Buckled	4,326.00 FS	*4,326.00 FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Necessary	67.00 FS	*67.00 FS
23	1		*FRONT FENDER SEAL- LH/RH	N/S Distorted	40.00 FS	*20.00 FS
24	1		*FRONT FENDER BRACE -LH/RH	N/S Distorted	164.00 FS	*84.00 FS
25	1		*FRONT FENDER CLOSING ELEMENT -LH/RH UPPER	N/S Damaged	44.00 FS	*22.00 FS
26	1		*FRONT FENDER CLOSING ELEMENT -LH/RH	N/S Damaged	286.00 FS	*143.00 FS
27	1		*FRONT FENDER SECURING BRACKET -LH/RH	N/S Damaged	34.00 FS	*17.00 FS
28	1		*FRONT WHEEL HOUSING LINER -LH/RH	N/S Torn	598.00 FS	*299.00 FS
29	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	N/S Damaged	114.00 FS	*57.00 FS
30	2		*INSCRIPTION S LINE	Necessary	266.00 FS	*266.00 FS
31	1		*BONNET	Distorted	7,363.00 FS	*7,363.00 FS
32	1		*BONNET ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
33	2		*BONNET LID HINGE LH/RH	Bent	382.00 FS	*382.00 FS
34	2		*BONNET HINGE COVER -LH /RH	Not Necessary	104.00 FS	*- FS
35	1		*BONNET GASS FILLED STRUR	Not Necessary	154.00 FS	*- FS
36	1		*BONNET CATCH HOOK	Not Necessary	110.00 FS	*- FS
37	1		*BONNET LID LOCK	Not Necessary	228.00 FS	*- FS
38	1		*BONNET LID LOCK BRACKET	Not Necessary	63.00 FS	*- FS
39	1		*BONNET LID LOCK CABLE	Not Necessary	109.00 FS	*- FS
40	1		*BONNET LID LOCK GRIP	Not Necessary	71.00 FS	*- FS
41	1		*BONNET LID LOCK CABLE	Necessary	82.00 FS	*82.00 FS
42	1		*BONNET LID LOCK ABLE COVER	Necessary	94.00 FS	*94.00 FS
43	2		*BONNET SEAL LH /RH	Necessary	46.00 FS	*46.00 FS
44	1		*BONNET SEAL FRONT	Necessary	119.00 FS	*119.00 FS
45	2		*BONNET SEAL UPPER FRONT	Necessary	89.00 FS	*89.00 FS
46	2		*HEADLIGHT MOUNTING LH/RH	Cracked	446.00 FS	*446.00 FS
47	2		*HEADLIGHT -LH/RH	Cracked	7,816.00 FS	*7,816.00 FS
48	2		*HEADLIGHT CONTROL UNIT -LH/RH	Not Necessary	2,474.00 FS	*- FS
49	1		*HEADLIGHT GAS DISCHARGE -LH/RH	N/S Damaged	906.00 FS	*453.00 FS
50	1		*VENT HOSE -LH	Distorted	97.00 FS	*97.00 FS
51	1		*VENT HOSE -RH	Not Necessary	26.00 FS	*- FS
52	2		*HEADLIGHT ASSEMBLY SPACER -LH/RH	Distorted	91.00 FS	*91.00 FS
53	1		*HEADLIGHT ADJUSTMENT ELEMENT	N/S Damaged	305.00 FS	*157.50 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*HEADLIGHT SPACER -LH/RH	N/S Damaged	97.00 FS	*48.50 FS
55	1		*HALDGEN FOG LAMP -LH/RH	N/S Missing	896.00 FS	*498.00 FS
56	1		*LED TURN SIGNAL -LH/RH	N/S Missing	2,362.00 FS	*1,181.00 FS
57	1		*HEADLIGHT NOZZLE CARRIER -LH/RH	N/S Smashed	456.00 FS	*278.00 FS
58	1		*HOSE FOR HEADLIGHT WASHER SYSTEM	*Check	215.00 FS	*- FS
59	1		*PUMP FOR HEADLIGHT WASHER SYSTEM	Missing	171.00 FS	*171.00 FS
60	1		*FLAT CONTACT HOUSING	Damaged	45.00 FS	*45.00 FS
61	1		*PUMP FOR WINDSCREEN WASHER SYSTEM	Not Necessary	137.00 FS	*- FS
62	1		*WASHER WATER RESERVOIR	Not Necessary	191.00 FS	*- FS
63	2		*SPRAY NOZZLE FOR FRONT WINDSCREEN -LH/RH	Not Necessary	230.00 FS	*- FS
64	1		*FRONT LOCK CARRIER	Cracked	1,437.00 FS	*1,437.00 FS
65	2		*BONDED RUBBER MOUNTING BRACET	Necessary	12.00 FS	*12.00 FS
66	1		*FRONT CROSS MEMBER -LOWER	*Check	333.00 FS	*- FS
67	1		*A/C CONDENSER	*Check	1,053.00 FS	*- FS
68	1		*A/C CONDENDER SEAL	*Check	53.00 FS	*- FS
69	1		*A/C SUCTION HOSE	Bent	730.00 FS	*730.00 FS
70	1		*A/C HOSE	Bent	541.00 FS	*541.00 FS
71	1		*A/C DISCHARGE HOSE	Bent	423.00 FS	*423.00 FS
72	1		*A/C SUCTION LINE	Bent	671.00 FS	*671.00 FS
73	1		*RADIATOR	Cracked	1,745.00 FS	*1,745.00 FS
74	2		*RADIATOR CROMMET -UPPER	Necessary	63.00 FS	*63.00 FS
75	2		*RADIATOR PROFILE RUBBER -LOWER	Necessary	143.00 FS	*143.00 FS
76	2		*ADDITIONAL RADIATOR	Distorted	1,899.00 FS	*1,899.00 FS
77	1		*RESERVOIR	Not Necessary	1,091.00 FS	*- FS
78	6		*RADIATOR COOLANT	Necessary	228.00 FS	*228.00 FS
79	1		*RADIATOR BRACKET	Necessary	17.00 FS	*17.00 FS
80	1		*RADIATOR END CAP	Necessary	38.00 FS	*38.00 FS
81	2		*RADIATOR TWIN FAN RING	*Check	535.00 FS	*- FS
82	1		*RADIATOR FAN -LH	Not Necessary	1,380.00 FS	*- FS
83	1		*RADIATOR FAN -RH	Not Necessary	1,509.00 FS	*- FS
84	1		*RADIATOR AIR GUIDE -LH/RH	N/S Damaged	64.00 FS	*32.00 FS
85	1		*RADIATOR AIR GUIDE -UPPER	Missing	48.00 FS	*48.00 FS
86	1		*RADIATOR AIR GUIDE -LOWER	Not Necessary	36.00 FS	*- FS
87	1		*RADIATOR AIR GUIDE -LH /RH FRONT	N/S Distorted	128.00 FS	*64.00 FS
88	2		*RADIATOR SEAL -LH/RH	*Check	60.00 FS	*- FS
89	2		*RADIATOR BEADING	*Check	94.00 FS	*- FS
90	1		*AIR FILER	Not Necessary	704.00 FS	*- FS
91	1		*INTAKE HOSE	*Check	412.00 FS	*- FS
92	1		*INTAKE MANIFOLD	Not Necessary	124.00 FS	*- FS
93	1		*WATER DRAINAGE HOSE	Not Necessary	37.00 FS	*- FS
94	1		*COMPRESSOR	Cut	8,629.00 FS	*8,629.00 FS
95	1		*THROTILE VALVE ADAPTER	*Check	1,581.00 FS	*- FS
96	1		*THROTILE VALVE CONTRIM ELEMENT	*Check	1,142.00 FS	*- FS
97	1		*ENGINE SUPPORT -LH	*Check	178.00 FS	*- FS
98	1		*ENGINE SUPPORT -RH	Not Necessary	113.00 FS	*- FS
99	1		*ENGINE MOUNTING	*Check	429.00 FS	*- FS
100	1		*ENGINE BRACKET	*Check	2,116.00 FS	*- FS
101	2		*FRONT SHOCK ABSORBER MOUNTING -LH/RH	Not Necessary	238.00 FS	*- FS
102	1		*FRONT FENDER SUPPORT -LH/RH	N/S Distorted	384.00 FS	*192.00 FS
103	2		*FRONT SIDE MEMBER -LH/RH	*Check	2,284.00 FS	*- FS
104	1		*FRONT SIDE MEMBER EXTENSION -LH	*Check	1,261.00 FS	*- FS
105	1		*FRONT SIDE MEMBER EXTENSION BRACKET -LH	*Check	40.00 FS	*- FS
106	1		*FRONT ALUMINIUM RIM LH	Not Necessary	3,020.00 FS	*- FS
107	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
108	1		*FRONT CROSS MEMBER	*Check	4,503.00 FS	*- FS
109	1		*FRONT WISHBONE -LH UPPER	*Check	840.00 FS	*- FS
110	1		*FRONT WISHBONE -LH LOWER	*Check	84.00 FS	*- FS
111	1		*FRONT WHEEL BEARING -LH	*Check	1,272.00 FS	*- FS
112	1		*FRONT WHEEL BEARING BRACKET -LH	*Check	587.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
113	1		*FRONT WHEEL HUB -LH	*Check	467.00 FS	*- FS
114	1		*FRONT WHEEL BEARING WITH ASSEMBLY	*Check	510.00 FS	*- FS
115	1		*HEADLIGHT LEVEL CONTROL WITH SENSOR -LH	*Check	851.00 FS	*- FS
116	1		*FRONT GAS SHOCK ABSORBER -LH	*Check	921.00 FS	*- FS
117	1		*FRONT ANTI ROLL BAR	*Check	783.00 FS	*- FS
118	1		*FRONT COUPLING ROD	*Check	145.00 FS	*- FS
119	1		*FRONT DRIVE SHAFT	Not Necessary	1,838.00 FS	*- FS
120	1		*FRONT STEERING GEAR	Not Necessary	6,361.00 FS	*- FS
121	1		*FRONT TRACK ROD LH	*Check	353.00 FS	*- FS
122	1		*SPLASH SHIELD	*Check	756.00 FS	*- FS
123	1		*SPLASH SHIELD CENTER	*Check	781.00 FS	*- FS
124	1		*FRONT DOOR LH	Dented	5,708.00 FS	*5,708.00 FS
125	1		*FRONT DOOR OUTER SEAL -LH	Necessary	463.00 FS	*463.00 FS
126	2		*FRONT DOOR SPACER	Not Necessary	5.00 FS	*- FS
127	1		*FRONT DOOR ATTACHMENT PARTS -LH	Not Necessary	102.00 FS	*- FS
128	2		*FRONT DOOR FOAM -LH	Not Necessary	63.00 FS	*- FS
129	1		*FRONT DOOR HINGE -LH (NPA)	Not Necessary	0.00 FS	*- FS
130	1		*FRONT DOOR HINGE LH LOWER (NPA)	Not Necessary	0.00 FS	*- FS
131	1		*FRONT DOOR CIVER LH	Not Necessary	396.00 FS	*- FS
132	1		*FRONT SIDE MIRROR EXTERIOR MOUNTING -LH	Not Necessary	1,752.00 FS	*- FS
133	1		*FRONT SIDE MIRROR CAP -LH	Not Necessary	461.00 FS	*- FS
134	1		*FRONT SIDE MIRROR TURN SIGNAL -LH	Not Necessary	181.00 FS	*- FS
135	1		*STATIC MIXER	Necessary	12.00 FS	*12.00 FS
136	1		*2 PACK EPOXY ADHESIVE	Necessary	122.00 FS	*122.00 FS
137	1		*ALUMINIUM POWDER	Necessary	637.00 FS	*637.00 FS
138	1		*HARDENER	Necessary	232.00 FS	*232.00 FS
139	1		*ALUMINIUM PRIMER	Necessary	233.00 FS	*233.00 FS
140	1		*CLEANING BLOCK	Necessary	96.00 FS	*96.00 FS
141	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
142	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
143	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
144	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
145	1		*SUNDRIES	*Check	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 112,637.00 58,965.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	900.00	500.00
3	TO REMOVE AND RENEW AIR CONDENSER ,ADDITIONAL RADIATOR AND RADIATOR ,CHECK ELECTRICAL FANS AND CONTROL UNIT TO CARRY OUT PRESSURE VACUUM AND REGAS	New	2,000.00	2,000.00
4	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	450.00	280.00
5	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS .INSPECT FOR DAMAGES	New	2,800.00	2,800.00
6	TO RENEW ALL TERNATOR ,THROTTLE BODY AND OTHER ENGINE COMPONENTS (*Check)	New	980.00	0.00
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	2,400.00
8	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	800.00
9	TO PLACE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
10	TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET ,BOTH FRONT FENDERS AND BOTH HEADLIGHT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT AND BOTH FRONT CHASSIS FRAME COVER PLATES AND BOTH FRONT CHASSIS FRAME TO ALIGN BACK BOTH CHASSIS MEMBERS INTO POSITION RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	19,000.00	8,400.00
11	TO RESPRAY FRONT BUMPER ,BONNE ,HINGES ,BOTH FRONT FENDERS ,BOTH FRONT FENDER TOP SUPPORT ,BOTH FRONT CHASSIS FRAME WITH COVERS ,BOTH UPPER A-PILLARS BOTH FRONT DOOR AND DOOR COVER	New	11,000.00	5,000.00
12	TO CARRY OUT ALUMINIUM PRIMER WORKS	New	980.00	980.00
13	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
14	TO RENEW LHS FRONT RIM WITH TYRE ,TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
15	TO CARRY OUT PRE-POST DIAGOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			45,374.00	26,944.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >