

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22002206/APA3Q2**Date:** 07/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700071285
Claimant Vehicle No :	SMX9079J	Insured Vehicle No :	SGG7100D
Date of Loss:	05/03/2022	Nature of Claim:	TP
		Claim No:	5962629350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX9079J		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC25602
Reg. Date:	04/02/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF35M1068018
Colour:	White	Odometer:	12153 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,312.00	8,068.96	5,243.04	39.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,252.00	4,252.00	4,000.00	48.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	21,564.00	12,320.96	9,243.04	42.86
+ GST 8.00/8.00% (\$\$)	1,725.12	985.68	739.44	42.86
Nett Amount (\$\$)	23,289.12	13,306.64	9,982.48	42.86
+ Car Rental (5.0 x S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		13,808.64		

INSPECTION

Date of Assignment:	15/03/2022		
Date Inspected:	15/03/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,423.00 FS	*1,138.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	433.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
4	1		*FRONT BUMPER SPOLER	Not Necessary	850.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	171.00 FS	*- FS
6	1		*FRONT BUMPER TRIM	Not Necessary	182.00 FS	*- FS
7	1		*FRONT PARKING AID SENSOR SUPPORT -RH	Not Necessary	43.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	43.00 FS	*- FS
9	1		*FRONT FENDER -RH	Buckled	1,445.00 FS	*1,156.00 FS
10	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
11	1		*FRONT FENDER BRACE -RH	Bent	98.00 FS	*77.68 FS
12	1		*FRONT FENDER BRACKET -RH	Bent	39.00 FS	*30.48 FS
13	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	37.00 FS	*- FS
14	1		*FRONT FENDER INSULATION	Not Necessary	48.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	260.00 FS	*- FS
16	1		*FRONT WHEEL HOUSING LINER COVER	Not Necessary	18.00 FS	*- FS
17	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
18	1		*HEADLIGHT MOUNTING -RH	Not Necessary	132.00 FS	*- FS
19	1		*HEADLIGHT -RH	Cracked	5,952.00 FS	*4,761.60 FS
20	1		*HEADLIGHT LEFT CYLINDER -RH	Not Necessary	231.00 FS	*- FS
21	1		*HEADLIGHT HOSE	Not Necessary	92.00 FS	*- FS
22	2		*FRONT WHEELARCH COVER -LH/RH	Necessary	1,132.00 FS	*904.80 FS
23	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	13,312.00 8,068.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF RHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER ,FRONT BUMPER LOWER SPOILER ,RHS FRONT FENDER ,RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS	New	4,500.00	2,050.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,252.00	4,252.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >