



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 6228E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (CONSISTENT)	BUCKLED	563.00	531.10
1	FRONT BUMPER RETAINER/LH (CONSISTENT)	DISTORTED	90.40	90.40
1	FRONT HEADLAMP/LH (CONSISTENT)	CRACKED	3,180.20	2,816.50
1	FRONT GRILLE (CONSISTENT)	SERVICEABLE	680.70	-
1	FRONT FENDER EMBLEM (CONSISTENT)	NOT NECESSARY	31.90	-
	LESS 25% DISCOUNT		-1,136.55	-859.50
			3,409.65	2,578.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRT NO PLATE (SN) (CONSISTENT)	DENTED	45.00	45.00
			45.00	45.00
	<b><u>LABOUR</u></b>			
	TO FOCUS HEADAMP & CHECK HEADLAMP WIRING FUNCTION.		55.00	20.00
	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS.	NOT NECESSARY	120.00	-
	TO CHECK COMPURERISED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REPAIR ,PANELBEAT ,ALIGN ON LEFT FRT FENDER & BONNET AND LABOUR TO REPLACE ABOVE PARTS.		800.00	200.00
	TO PUTTY ,PRIMER & SPRAY PAINT ON LEFT FRT FENDER ,FRT BUMPER & AFFECTED FRT BONNET USING 2K REARLESCENT PAINT.		900.00	250.00
			1,995.00	470.00
	<b>GRAND TOTAL</b>		<b>5,449.65</b>	<b>3,093.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,450.00</b>

Report Ref No. CC4/ASM22002208/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.