

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002223/KQY3N2**Date:** 30/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00049722100

**Claimant Vehicle No :** SFF2676J **Insured Vehicle No :** SGT8256M

Date of Loss: 25/02/2022 Nature of Claim: TP Claim No: SNM22D201393/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SFF2676J**

Make & Model: HONDA CIVIC, 1.6 VTI-S (A) Engine No: R16B11001804

Reg. Date: 01/10/2013 (Man. Year: 2012) Chassis No: JHMFB1630CS201302

Colour: Metallic Black Odometer: 120945 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: KAPSEN 7 mm Rear Left Side: KAPSEN 7 mm

Front Right Side: KAPSEN 7 mm Rear Right Side: KAPSEN 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,524.80	1,866.00	3,658.80	66.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	850.00	1,550.00	64.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,924.80</b>	<b>2,716.00</b>	<b>5,208.80</b>	<b>65.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>(S\$)</b>	7,924.80	2,200.00	5,724.80	72.24
<b>+ GST 7.00/7.00% (S\$)</b>	554.74	154.00	400.74	72.24
<b>Nett Amount (S\$)</b>	<b>8,479.54</b>	<b>2,354.00</b>	<b>6,125.54</b>	<b>72.24</b>

**INSPECTION**

Date of Assignment: 09/03/2022

Date Inspected: 09/03/2022 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)  
176 SIN MING DRIVE, #05-14  
Singapore 575721

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2022)
<b>Parts:</b>	143	HONDA CIVIC 1.6 VTI-S (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFF2676J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE HONDA EMBLEM	Serviceable	65.00 FL	*- FL
2	1		*RADIATOR GRILLE	Serviceable	487.00 FL	*- FL
3	1		*RADIATOR GRILLE CHROME MOULDING	Serviceable	188.00 FL	*- FL
4	1		*FRONT BUMPER	Bent	1,035.00 FL	*709.60 FL
5	1		*FRONT BUMPER SIDE RETAINER	N/s Distorted	130.00 FL	*32.20 FL
6	1		*FRONT BUMPER IMPACT ABSORBER	Serviceable	180.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Repair	553.00 FL	*- FL
8	1		*FRONT FENDER N/S	Buckled	918.00 FL	*477.00 FL
9	1		*FRONT FENDER INNER COWLING N/S	Serviceable	185.00 FL	*- FL
10	1		*AIR INTAKE HOUSING	Cracked	498.00 FL	*132.20 FL
11	1		*FRONT FOGLAMP GARNISH N/S	Dented/Mtg Distorted	248.00 FL	*28.60 FL
12	1		*SUPPORT PANEL	Repair	498.00 FL	*- FL
13	1		*HEADLAMP BRACKET N/S	Bent	169.00 FL	*39.20 FL
14	1		*HEADLAMP N/S	Cut	1,452.00 FL	*846.20 FL
15	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
16	12		*FRONT BUMPER CLIPS	Necessary	54.00 FS	*54.00 FS
17	8		*FRONT SUPPORT TOP PANEL GARNISH CLIPS	Not Necessary	36.00 FS	*- FS
18	10		*FRONT FENDER INNER COWLING N/S CLIPS	Not Necessary	45.00 FS	*- FS
19	1		*FRONT LICENCE PLATE & FRAME	Serviceable	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,846.00</b>	<b>2,319.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,321.20	453.00
<b>Total Parts (\$\$)</b>	<b>5,524.80</b>	<b>1,866.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	400.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	100.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	400.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,400.00</b>	<b>850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >