

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122002224/KTY3N2**Date:** 20/05/2022**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNC9432X**Insured Vehicle No :** WC2834J

Date of Loss: 08/03/2022

Nature of Claim:

TP

Claim No: CDMFG22000437

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC9432X**

Make & Model: TESLA MODEL 3 STANDARD RANGE, (A)

Engine No: HIDDEN

Reg. Date: 25/11/2021 (Man. Year: 2021)

Chassis No: LRW3F7FA3MC384670

Colour: Metallic Pearl White

Odometer: 6599 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40ZR19

Rear Tyre Size: 235/40ZR19

Front Left Side: Pirelli 9 mm

Rear Left Side: Pirelli 9 mm

Front Right Side: Pirelli 9 mm

Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,277.60	0.00	1,277.60	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	320.00	1,170.00	78.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,767.60	320.00	2,447.60	88.44

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 10/03/2022 Inspected At:

Optima Werkz Pte Ltd (HQ)

10 Ang Mo Kio Industrial Park 2A, #01-05 AMK

Autopoint

Singapore 568047

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 May 2022)

Parts: 143 TESLA MODEL 3 STANDARD RANGE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC9432X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	633.55 FL	*- FL
2	2		*REAR PARKING SENSOR	Serviceable	320.00 FL	*- FL
3	1		*REAR BUMPER REVERSE SENSOR RETAINER LH	Serviceable	10.00 FL	*- FL
4	1		*REAR REINFORCEMENT	Repair	367.12 FL	*- FL
5	1		*REAR BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
					Sub Total (\$\$)	1,410.67 0.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	133.07 0.00
					Total Parts (\$\$)	1,277.60 0.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	600.00	100.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR FENDER LH,REAR BUMPER & ETC	New	400.00	220.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	0.00
4	TO WHEEL ALIGNMENT & BALANCING	New	100.00	0.00
5	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
6	TO CHECK WIIRNG & ELECTRICAL SYSTEM & ETC	New	120.00	0.00
Gross Labour Cost (\$\$)			1,490.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >