



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 8258U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LH/F DOOR SHELL (SN)	DENTED	1,756.67	1,756.67
1	LH/F DOOR INSULATION (SN)	NECESSARY	21.36	21.36
1	LH/F DOOR SEALING RAIL (SN)	NOT NECESSARY	104.89	-
1	LH/F DOOR WEATHERSTRIP (SN)	NECESSARY	313.32	313.32
1	LH/R DISC WHEEL (SN)	NOT NECESSARY	710.38	-
1	LEFT WING MIRROR ASSEMBLY (SN)	NOT NECESSARY	868.19	-
1	REAR LEFT RIM (SN)	NOT NECESSARY	60.00	-
			3,834.81	2,091.35
	<b><u>LABOUR</u></b>			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTING.		380.00	380.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR .		480.00	480.00
	REMOVE & REPLACE FRONT LEFT DOOR & REPAIR REAR LEFT DOOR AND REAR LEFT FENDER .		1,920.00	960.00
	RESPRAY FRONT LEFT DOOR ,REAR LEFT DOOR & REAR LEFT FENDER .		2,800.00	2,400.00
			6,120.00	4,760.00
	<b>GRAND TOTAL</b>		<b>9,954.81</b>	<b>6,851.35</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>6,851.35</b>

Report Ref No. CS/AIS22002225/Evy3q2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.