

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002226/UVY3N2**Date:** 23/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00147242100

**Claimant Vehicle
No :** SJE2820S**Insured Vehicle
No :** GBK4876G

Date of Loss: 07/03/2022

Nature of Claim: TP

Claim
No: SNM22D201629/C03/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJE2820S**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4752869

Reg. Date: 21/04/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106104767

Colour: Red

Odometer: 193269 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Premio 6 mm

Rear Left Side:

Premio 6 mm

Front Right Side: Premio 6 mm

Rear Right Side:

Premio 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,295.22	2,901.75	2,393.47	45.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,820.00	1,850.00	50.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,965.22	4,721.75	4,243.47	47.33
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	8,965.22	3,750.00	5,215.22	58.17
+ GST 7.00/7.00% (S\$)	627.57	262.50	365.07	58.17
Nett Amount (S\$)	9,592.79	4,012.50	5,580.29	58.17

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 11/03/2022

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE2820S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	505.00 FL	*505.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BUMPER SIDE RETAINER O/S	Bent	35.00 FL	*35.00 FL
4	1		*O/S TAILLAMP	Scratched	268.00 FL	*268.00 FL
5	3		*O/S TAILLAMP CLIPS	Not Necessary	15.00 FL	*- FL
6	1		*O/S REAR FENDER	Badly Dented	918.00 FL	*918.00 FL
7	1		*O/S REAR FENDER INNER COWLING	Not Necessary	46.80 FL	*- FL
8	6		*O/S REAR FENDER INNER COWLING CLIPS	Not Necessary	30.00 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	118.00 FL	*118.00 FL
10	1		*O/S REAR DOOR	Dented/Bent	1,075.00 FL	*1,075.00 FL
11	1		*O/S REAR DOOR OUTER MOULDING	Not Necessary	178.00 FL	*- FL
12	1		*O/S REAR DOOR OUTER PROTECTOR	Bent	125.00 FL	*125.00 FL
13	1		*O/S REAR DOOR OUTER HANDLE	Cut	155.00 FL	*155.00 FL
14	1		*O/S REAR DOOR LOCK	Serviceable	485.00 FL	*- FL
15	1		*O/S REAR DOOR INNER TRIM BOARD	Not Necessary	355.80 FL	*- FL
16	1		*O/S REAR DOOR POWER WINDOW MOTOR	Not Necessary	509.10 FL	*- FL
17	1		*O/S REAR DOOR REGULATOR	Not Necessary	225.80 FL	*- FL
18	2		*O/S REAR DOOR FRAME STICKER	Necessary	110.00 FL	*110.00 FL
19	1		*O/S REAR WHEEL BEARING	Not Necessary	675.80 FL	*- FL
20	1		*O/S REAR WHEEL RIM	Warped	562.50 FS	*350.00 FS
21	1		*O/S REAR TYRE	Serviceable	250.00 FS	*- FS
22	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,762.80	3,739.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,467.58	837.25
Total Parts (\$\$)	5,295.22	2,901.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	40.00
2	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	120.00	60.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	60.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR	New	120.00	80.00
6	TO DROP REAR AXLE AND SUSPENSION ASSY,REMOVE AND RENEWAL OF NECESSARY PARTS,TO CONDUCT FINAL CHECKING AND TESTING	New	250.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
8	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	50.00	0.00
9	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,200.00	600.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	800.00
Gross Labour Cost (\$\$)			3,670.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >