

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002231/ATY3N2**Date:** 07/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00004752201

Claimant Vehicle No : SKT9253S **Insured Vehicle No :** GZ2054L

Date of Loss: 29/01/2022 Nature of Claim: TP Claim No: SNM22D201249/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9253S**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2148720A

Reg. Date: 25/06/2015 (Man. Year: 2015) Chassis No: SJNFEAJ11U1398148

Colour: White Odometer: 90184 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R18 Rear Tyre Size: 225/50R18

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,018.67	2,950.10	1,068.57	26.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	820.00	980.00	54.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,818.67	3,770.10	2,048.57	35.21
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	5,818.67	3,000.00	2,818.67	48.44
+ GST 7.00/7.00% (S\$)	407.31	210.00	197.31	48.44
Nett Amount (S\$)	6,225.98	3,210.00	3,015.98	48.44

INSPECTION

Date of Assignment: 08/03/2022

Date Inspected: 14/03/2022 Inspected At: Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2022)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKT9253S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Deformed	876.40 FN	*876.40 FN
2	1		*REAR BUMPER SIDE RETAINER LH	Necessary	49.00 FN	*49.00 FN
3	10		*REAR BUMPER CLIPS	Necessary	55.00 FN	*30.00 FN
4	1		*REAR BUMPER REINFORCEMENT	Dented	691.50 FN	*619.00 FN
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Dented	126.40 FN	*126.40 FN
6	1		*REAR BUMPER REFLECTOR LH	Not Necessary	61.90 FN	*- FN
7	1		*REAR BUMPER TOW COVER	Not Necessary	35.20 FN	*- FN
8	1		*TAIL LAMP LH	Cracked	346.90 FN	*346.90 FN
9	1		*REAR WHEEL ARC GARNISH LH	Cracked	540.50 FN	*540.50 FN
10	8		*REAR WHEEL ARC GARNISH CLIPS	Necessary	44.00 FN	*20.00 FN
11	1		*TAIL GATE REFLECTOR	Cut	254.40 FN	*254.40 FN
12	1		*REAR END PANEL	Repair	482.80 FN	*- FN
13	1		*REAR END PANEL TOP TRIM	Not Necessary	63.90 FN	*- FN
14	4		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	22.00 FN	*- FN
15	1		*REAR BUMPER SPONGE	Cracked	126.40 FN	*126.40 FN
16	1		*REAR BUMPER REFLECTOR CHROME (ACC)	Necessary	120.00 FS	*60.00 FS
17	1		*REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
18	1		*TAIL LAMP CHROME (ACC)	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,396.30	3,249.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	377.63	298.90
Total Parts (\$\$)	4,018.67	2,950.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	60.00	30.00
2	TO TUFF COAT AFFECTED AREAS	New	120.00	40.00
3	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
4	TO RESPRAY AFFECTED AREAS	New	800.00	400.00
5	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR REAR END PANEL,REAR LH FENDER AND ALIGNED ALL PARTS	New	700.00	300.00
Gross Labour Cost (\$\$)			1,800.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >