

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002232/KTY3N2**Date:** 28/03/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN00108352103

Claimant Vehicle No : YN9523D **Insured Vehicle No :** XE4335Y

Date of Loss: 21/02/2022 Nature of Claim: TP Claim No: SNM22D201303/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN9523D**

Make & Model: UD TRUCKS PKC8ELN5EP, 7.0 D (M) Engine No: GH7208401

Reg. Date: 01/10/2015 (Man. Year: 2015) Chassis No: PKC8E30558

Colour: White Odometer: 225378 km

Engine Capacity: 7013 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 11R22.5 Rear Tyre Size: 11R22.5(D)

Front Left Side: West Lake 8 mm Rear Left Side: tracmax 9/9 mm

Front Right Side: West Lake 8 mm Rear Right Side: tracmax 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,880.00	3,470.00	410.00	10.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,400.00	700.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,980.00	4,870.00	1,110.00	18.56
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	5,980.00	4,300.00	1,680.00	28.09
+ GST 7.00/7.00% (S\$)	418.60	301.00	117.60	28.09
Nett Amount (S\$)	6,398.60	4,601.00	1,797.60	28.09

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 09/03/2022 Inspected At: Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Mar 2022)	
Parts:	N/A	UD TRUCKS PKC8ELN5EP 7.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN9523D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	3		*HORIZONTAL SOLID WOODEN BAR	Cracked	1,500.00 F	*1,500.00 F	
2	1		*REAR CARGO SIDE GATE (WOODEN)-LH	Cracked	850.00 F	*850.00 F	
3	1		*REAR CARGO SIDE WOODEN BRACKET-LH (3 Pcs)	Bent (2 Pcs only)	300.00 F	*200.00 F	
4	1		*REAR CARGO SIDE WOODEN RAILING (ONG LYE PING)-LH	Cracked	800.00 F	*800.00 F	
5	1		*REAR CARGO SIDE WOODEN RAILING (ONG LYE PING) BRACKET-LH (6 Pcs)	Bent (4 Pcs only)	180.00 F	*120.00 F	
6	1		*REAR WHEEL TOP COVER-LH	Serviceable	250.00 F	*- F	
					Total Parts (S\$)	3,880.00	3,470.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	800.00	600.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	800.00	450.00
3	TO SUPPLY & ADJUST THE CARGO ALIGNMENT	New	500.00	350.00
			Gross Labour Cost (\$\$)	2,100.00
				1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >