

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002233/TVY3E2

Date: 25/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00116792100
Claimant Vehicle No: FBS3489E Insured Vehicle No: GBF3781D
Date of Loss: 19/02/2022 Nature of Claim: TP Claim No: SNM22D201285/C03/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBS3489E
Make & Model: HONDA ADV150, 149cc ABS CVT Engine No: KF61E1034507
Reg. Date: 24/03/2021 (Man. Year: 2020) Chassis No: MH1KF6110MK034512
Colour: Grey Odometer: 0 km
Engine Capacity: 149 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80R14 Rear Tyre Size: 130/70R14
Front Left Side: Federal 5 mm Rear Left Side: Federal 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,889.00	2,223.00	1,666.00	42.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	885.00	320.00	565.00	63.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,774.00	2,543.00	2,231.00	46.73
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	4,774.00	2,050.00	2,724.00	57.06
+ GST 7.00/7.00% (S\$)	334.18	143.50	190.68	57.06
Nett Amount (S\$)	5,108.18	2,193.50	2,914.68	57.06

INSPECTION

Date of Assignment: 29/03/2022
Date Inspected: 09/03/2022 Inspected At: New Union Company (HQ)
BLK 9004 TAMPINES STREET 93 #01-106
Singapore 528838
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 May 2022)	
Parts:	N/A	HONDA ADV150 149cc ABS CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS3489E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE COVER LHS	Cut	140.00 F	*140.00 FL
2	1		*SIDE COVER RHS	Cut	140.00 F	*140.00 FL
3	1		*FRONT NUMBER PLATE	Not Necessary	25.00 F	*- FL
4	2		*WHEEL BEARINGS, FRONT	Not Necessary	80.00 F	*- FL
5	1		*RIM REPAIR	Not Necessary	120.00 F	*- FL
6	1		*RIM SHAFT, FRONT	Not Necessary	65.00 F	*- FL
7	1		*BRAKE LEVER, LHS	Not Necessary	29.00 F	*- FL
8	1		*BRAKE LEVER, RHS	Cut	49.00 F	*49.00 FL
9	1		*SIGNAL LAMP, FRONT - RHS	Not Necessary	95.00 F	*- FL
10	1		*FRONT COVER UPPER	Cut	169.00 F	*169.00 FL
11	1		*FRONT COVER LOWER	Cut	89.00 F	*89.00 FL
12	1		*COVER FLOOR SIDE, RHS	Cut	169.00 F	*169.00 FL
13	2		*HANDLE BALANCER	Cut	80.00 F	*80.00 FL
14	1		*HANDLE BAR	Bent	170.00 F	*170.00 FL
15	2		*HANDLE GRIP RUBBER	Not Necessary	40.00 F	*- FL
16	1		*FRONT FENDER	Cut	165.00 F	*165.00 FL
17	1		*HEAD LAMP ASSY	Cracked	470.00 F	*470.00 FL
18	1		*BRAKE PUMP, HAND	Cut	260.00 F	*260.00 FL
19	1		*SIDE MIRROR	O/s Cut/N/s Not Necessary	130.00 F	*65.00 FL
20	1		*WINDSHIELD BRACKET	Not Necessary	65.00 F	*- FL
21	1		*WINDSHIELD VISOR	Not Necessary	120.00 F	*- FL
22	1		*STEERING CORN	Not Necessary	120.00 F	*- FL
23	1		*FORK OIL	Not Necessary	20.00 F	*- FL
24	1		*FORK SEAL SET (PAIR)	Not Necessary	60.00 F	*- FL
25	1		*PINION FOOT REST, RHS	Not Necessary	85.00 F	*- FL
26	1		*HEAD LAMP STAY BRACKET	Not Necessary	220.00 F	*- FL
27	1		*RACKING, CARRIER	Cut	180.00 F	*180.00 FL
28	1		*BRAKE DISC, FRONT REPAIR	Not Necessary	110.00 F	*- FL
29	1		*RIM BUSS, FRONT	Not Necessary	35.00 F	*- FL
30	1		*EXHAUST COVER PROTECTOR, REAR	Cut	117.00 F	*117.00 FL
31	1		*EXHAUST COVER PROTECTOR, SIDE	Bent	109.00 F	*109.00 FL
32	1		*EXHAUST COVER PROTECTOR, FRONT	Cut	98.00 F	*98.00 FL
33	1		*EXHAUST GASKET	Not Necessary	65.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,889.00	2,470.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	247.00
Total Parts (\$\$)	3,889.00	2,223.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	65.00	0.00
2	LABOUR CHARGE	New	350.00	200.00
3	FORK ASSY	New	120.00	120.00
4	CHASSIS	New	350.00	0.00
Gross Labour Cost (\$\$)			885.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >