

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002236/KQY3Q2**Date:** 14/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00101672104

Claimant Vehicle No : SLD2585C **Insured Vehicle No :** SKK9940P

Date of Loss: 01/03/2022 Nature of Claim: TP Claim No: SNM22D201478/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD2585C**

Make & Model: TOYOTA ALLION A15, 1.5 (A) Engine No: 1NZD141031

Reg. Date: 05/09/2008 (Man. Year: 2008) Chassis No: NZT2603030361

Colour: Metallic Blue Odometer: 241885 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Grenlander 9 mm Rear Left Side: Grenlander 8 mm

Front Right Side: Grenlander 9 mm Rear Right Side: Grenlander 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,339.55	7,793.00	5,546.55	41.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,435.00	3,740.00	1,695.00	31.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,774.55	11,533.00	7,241.55	38.57
Approved Total (Overridden) (\$\$)		9,100.00		
Nett Amount (\$\$)	18,774.55	9,100.00	9,674.55	51.53

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 09/03/2022 Inspected At: Trust Autoworks - Ang Mo Kio (HQ)
Blk 5035, #01-345 Ang Mo Kio Industrial Pk 2
Singapore 569538

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2022)
Parts:	143	TOYOTA ALLION A15 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD2585C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	855.10 FL	*855.10 FL
2	2		*REAR BOOT LID HINGE	Repair	155.70 FL	*- FL
3	1		*REAR BOOT LID INNER LOCK	Dented	405.10 FL	*301.00 FL
4	1		*REAR BOOT LID INSULATOR	Serviceable	208.10 FL	*- FL
5	1		*REAR BOOT LID EMBLEM AL	Necessary	35.10 FL	*35.10 FL
6	1		*REAR BOOT LID EMBLEM LOGO	Necessary	55.20 FL	*55.20 FL
7	1		*REAR BOOT LID EMBLEM A 1.5	Necessary	35.50 FL	*35.50 FL
8	1		*REAR BOOT LID OUTER CHROME HANDLE	Warped	197.10 FL	*197.10 FL
9	2		*REAR NO PLATE LAMP	Serviceable	76.20 FL	*- FL
10	1		*REAR BOO RUBBER (50%)	Distorted / Dented	168.83 FS	*112.55 FS
11	1		*REAR END PANEL	Bent	577.35 FL	*577.35 FL
12	1		*REAR END PANEL INNER GARNISH	Dented	195.20 FL	*195.20 FL
13	1		*REAR O/S FENDER	Buckled	985.70 FL	*985.70 FL
14	1		*REAR WINDSCREEN MOULDING	Necessary	105.60 FL	*105.60 FL
15	2		*REAR FENDER INNER SHIELD	Serviceable	210.20 FL	*- FL
16	1		*REAR N/S FENDER AIR DUCT	Serviceable	195.70 FL	*- FL
17	2		*REAR FENDER INNER TRIM	Cracked	970.40 FL	*970.20 FL
18	1		*REAR BUMPER	Bent	1,045.95 FL	*1,045.95 FL
19	2		*REAR BUMPER BRACKETS	Bent	210.60 FL	*210.60 FL
20	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	150.60 FL	*75.30 FL
21	1		*REAR BUMPER TOW COVER	No such part	37.20 FL	*- FL
22	1		*REAR SPARE TYRE PANEL	Bent / Buckled	855.70 FL	*855.70 FL
23	2		*REAR BOOT SIDE FLOOR PANEL	Repair	574.20 FL	*- FL
24	1		*REAR SPARE TYRE COVER BOARD	Dented	295.10 FL	*295.10 FL
25	1		*REAR EXHAUST SILENCER	Repair	971.10 FL	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Repair	95.20 FL	*- FL
27	1		*REAR AXLE ASSY	Serviceable	2,017.30 FL	*- FL
28	1		*REAR N/S SHOCK ABSORBER	Serviceable	225.10 FL	*- FL
29	1		*REAR N/S HUB ASSY	Serviceable	498.10 FL	*- FL
30	1		*FRONT BUMPER	Cracked	1,050.80 FL	*1,020.10 FL
31	1		*FRONT BUMPER REINFORCEMENT	Repair	455.70 FL	*- FL
32	1		*FRONT BUMPER LOWER GRILLE	Dented	235.60 FL	*145.60 FL
33	1		*FRONT RADIATOR GRILLE	Mtg Cracked	287.50 FL	*287.50 FL
34	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
35	1		*REAR NO PLATE	Dented	40.00 FS	*40.00 FS
36	1		*REAR REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
37	1		*REAR REVERSE CAMERA	Serviceable	300.00 FS	*- FS
38	1		*REAR SPARE TYRE PANEL BLACK INSULATOR	Necessary	200.00 FS	*120.00 FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	55.00 FS	*40.00 FS
40	10		*REAR BUMPER CLIP	Necessary	25.00 FS	*25.00 FS
41	1		*FRONT BUMPER SPONGE	Serviceable	175.20 FL	*- FL
42	1		*REAR BUMPER SPONGE	Cracked	162.30 FL	*162.30 FL
43	1		*REAR ANTENNA	Cracked	197.20 FL	*197.20 FL
44	2		*REAR TAIL-LAMP ASSY	Mtg Cracked	1,100.20 FL	*757.00 FL
45	1		*REAR TAIL-LAMP PANEL	N/S Bent	510.40 FL	*255.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	17,443.13	10,198.15
					- List Item Discount on L Items 25.00/25.00% (S\$)	4,103.58	2,405.15
					Total Parts (S\$)	13,339.55	7,793.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING ETC	New	1,800.00	1,600.00
2	TO PUTTY & SPRAY PAINT ON REAR ACCIDENT AFFECTED PORTION	New	1,800.00	1,400.00
3	CHECK /RECONNECT WIRING	New	45.00	30.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	200.00	120.00
5	CHECK & REALIGN FOUR WHEEL	New	90.00	0.00
6	TO SET VEHICLE ON CHASSIS BENT & TO RESET CHASSIS	New	350.00	250.00
7	REMOVE/RENEW REAR UNDERCARRIAGES	New	550.00	0.00
8	REMOVE /REFIT REAR WINDSCREEN GLASS TO FACILITATE REPAIR	New	120.00	120.00
9	REMOVE /REFIT ROOF LINING TO FACILITATE REPAIR	New	180.00	100.00
10	REMOVE/REPAIR REAR EXHAUST SILENCER	New	150.00	60.00
11	REMOVE/REFIT FUEL TANK TO FACILITATE REPAIR	New	100.00	60.00
12	TOWING	New	50.00	0.00
Gross Labour Cost (\$\$)			5,435.00	3,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >