

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002237/ATY3S2**Date:** 27/05/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00013792200
<b>Claimant Vehicle No :</b>	SJG4842E	<b>Insured Vehicle No :</b>	SMX2956Z
Date of Loss:	02/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D201542/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJG4842E</b>		
Make & Model:	TOYOTA PICNIC, 2.0 (A)	Engine No:	1AZ5780102
Reg. Date:	02/07/2008 (Man. Year: 2008)	Chassis No:	JTEGH23B800025725
Colour:	Green	Odometer:	269281 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Rotalla 6 mm	Rear Left Side:	Rotalla 6 mm
Front Right Side:	Rotalla 6 mm	Rear Right Side:	Rotalla 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,153.25	1,610.20	2,543.05	61.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	810.00	1,670.00	67.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,633.25</b>	<b>2,420.20</b>	<b>4,213.05</b>	<b>63.51</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		

**Nett Amount (S\$)**

**6,633.25**

**1,900.00**

**4,733.25**

**71.36**

---

INSPECTION

Date of Assignment: 09/03/2022

Date Inspected: 09/03/2022

Estimated Period of Repair: 4.0 days

Inspected At:

Sin Yu Sin Workshop (HQ)  
1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)  
Singapore 417883

---

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
<b>Parts:</b> M1-MPV	TOYOTA PICNIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJG4842E)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	580.40 FL	*580.40 FL
2	1		*FRONT BUMPER SIDE RETAINER L/R	N/s Necessary	88.20 FL	*44.10 FL
3	1		*FRONT BUMPER FOG LAMP LH	Cracked	416.40 FL	*318.00 FL
4	1		*FRONT HEADLAMP LH	Cut	586.10 FL	*586.10 FL
5	1		*FRONT FENDER LH	Repair	848.90 FL	*- FL
6	1		*FRONT FENDER VVT-I EMBLEM LH	Necessary	45.00 FL	*45.00 FL
7	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	135.00 FL	*- FL
8	1		*FRONT LOWER ARM LH	Not Necessary	390.80 FL	*- FL
9	1		*FRONT SHOCK ABSORBER LH	Not Necessary	522.30 FL	*- FL
10	1		*FRONT KNUCKLE LH	Not Necessary	547.70 FL	*- FL
11	1		*FRONT KNUCKLE BEARING LH	Not Necessary	230.20 FL	*- FL
12	1		*FRONT SPORT RIM LH	Cut	450.00 FS	*400.00 FS
13	1		*FRONT TYRE LH	Not Necessary	350.00 FS	*- FS
14	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
15	1		*FRONT FENDER INNER TRIM CLIP LH	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,251.00</b>	<b>2,003.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,097.75	393.40
<b>Total Parts (\$\$)</b>	<b>4,153.25</b>	<b>1,610.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT WIRING.	New	80.00	30.00
2	TO REMOVE, CHECK & REPLACE FRONT UNDERCARRIAGE PARTS.	New	250.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT.	New	150.00	80.00
4	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS.	New	1,000.00	300.00
5	TO SPRAY PAINTING ON AFFECTED AREA.	New	1,000.00	400.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,480.00</b>
				<b>810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >