## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH7557Y
Make : HYUNDAI
Model : IONIQ(G2)

Date: 07/03/22

Insurance: CHINA TAIPING MVA: MS. LOKE YY

| Qty  | Parts Description / L   | abour            | Туре | Unit Price | Amount    |
|--|---|------------------|------|------------|-----------|
| aty  |   |                  |      |            | Ry\$459.4 |
|  | 1 REAR BUMPER COVER   |                  |      |            | 4 \$22.0  |
|  | 10 REAR BUMPER CLIPS  1 REAR BUMPER SIDE BRACKET LH  1 REAR BUMPER CENTRE MOULDING ASSY |                  |      |            | ₩ \$55.8  |
|  |   |                  |      |            | 太 \$451.3 |
|  |   |                  |      |            | x \$41.   |
|  | 1 REAR BUMPER REFLECTOR LAMP LH   |                  |      |            | , , ,     |
|  |   | SUB TOTAL        |      |            | \$1,029   |
|  |   | LESS 20%         |      |            | \$205     |
|  |   | DISCOUNTED TOTAL |      |            | \$823     |
|  |   | SOLH             |      |            | ner \$100 |
| REAR FENDER ADVERTISEMENT LOGO L<br>REAR FENDER ADVERTISEMENT LOGO F |   |                  |      |            | \$100     |
|  |   | JO KIT           |      |            | × \$50    |
|  | REAR BUMPER RUBBER MAT  |                  |      |            | \$250     |
|  | Labour Charge   |                  |      |            | 350       |
|  | PANEL BEATING   |                  |      |            | \$000     |
|  | SPRAY PAINTING CHARGE   |                  |      |            | 250 \$300 |
|  | REMOVE/REFIX REVERSE SENSOR   |                  |      |            | 30 \$80   |
|  | TEMO VERTER DE L'ESTE   | TOTAL LABOUF     | ₹    |            | \$980     |
|  |   | ESTIMATE TOTAL   | L    |            | \$2,053   |
|  |   |                  |      |            |           |
|  |   |                  |      |            |           |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taylor 9749749

W/ 7/3/22 8 445

22 dens

Remy offer report

tensphie Chhanderson

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal medincation(s) is allowed.
- Supplementary item(s) in as the resurveyed and is subject to that approval that insurance Company

Acknowledged by Repairer

Signature:

Date:



eturned to Service Reception upon collection

## comfortDelGro Engineering Pte Ltd

Date/Time: 07.03.2022 14:26

Page : 1

JOB CARD Sales Order: 4181217 JC NO305507903 ARC Repair TP(CLSO)1 eam: MILEAGE EGN NO.: SH 7557Y STOMER COMFORT TRANSPORTATION PTE LTD FUEL /MS HYUNDAI 7010045 E.....1/2..... STOMER NO 07.03.2022 11:05 383 SIN MING DRIVE IONIQ(G2) Singapore SINGAPORE 575717 TARGET DATE 65508755 OF MANU. 26.06.2019 .. (R) (P) COMPLETION DATE TIME. ASSIS CODE KMHC851CVKU164245 COUNT CARD NO. JOB DESCRIPTION ccident Date: 06.03.2022 IATURE: 3P 06.03.2022 ' DESCRIPTION LABOR CODE :/NO CKED & PASSED OUT BY: CUSTOMER'S SIGNATURE SERVICE ADVISOR Exit Pass wledgement Slip Vehicle No.: SH 7557Y SH 7557Y Date Name of Service Adviso Signature/Date of Service Advisor

To be kept by Security Guard