

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002244/AGA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100392899
<b>Claimant Vehicle No :</b>	SJF1398X	<b>Insured Vehicle No :</b>	GBB7115Y
Date of Loss:	11/02/2022	Nature of Claim:	TP
		Claim No:	6112599862SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJF1398X</b>	Engine No:	63805353
Make & Model:	PORSCHE CAYENNE, 3.6 (A)	Chassis No:	WP1ZZZ9PZ8LA04247
Reg. Date:	13/07/2007 (Man. Year: 2007)	Odometer:	149462 km
Colour:	Black		
Engine Capacity:	3598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/35 R21	Rear Tyre Size:	295/35 R21
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,480.00	5,267.70	3,212.30	37.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	760.00	710.00	48.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,950.00</b>	<b>6,027.70</b>	<b>3,922.30</b>	<b>39.42</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,950.00</b>	<b>4,800.00</b>	<b>5,150.00</b>	<b>51.76</b>
<b>+ Loss of Use (4.0 x S\$150.00/day) (S\$)</b>		600.00		
<b>Nett Liability (S\$)</b>		<b>5,400.00</b>		

INSPECTION

Date of Assignment:	09/03/2022	
Date Inspected:	09/03/2022	Inspected At: Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,950.00 F	*1,950.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	190.00 F	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Cracked	960.00 F	*960.00 FL
5	1		*REAR BUMPER DIFFUSER	Deformed	1,550.00 F	*1,550.00 FL
6	1		*REAR BUMPER TOW COVER	Not Necessary	85.00 F	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	1,287.00 F	*- FL
8	1		*REAR BUMPER SPONGE	Cracked	158.00 F	*158.00 FL
9	6		*REVERSE SENSOR	Damaged (3 PCS ONLY)	2,130.00 F	*1,065.00 FL
10	6		*REVERSE SENSOR HOLDER	Necessary	120.00 F	*120.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	8,480.00	5,853.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	585.30
Total Parts (\$)	8,480.00	5,267.70

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	500.00	300.00
2	SPRAY PAINTING	New	500.00	250.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	120.00	60.00
5	TO PERFORM DIANOGSTIC TEST	New	250.00	120.00
<b>Gross Labour Cost (\$)</b>			<b>1,470.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >