

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21012730/ETY3E2-1

Date: 10/03/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLK6263T **Insured Vehicle No :** SLS8247K
Date of Loss: 10/12/2021 Nature of Claim: TP Claim No: MFL2021D0005535

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK6263T**
Make & Model: VOLKSWAGEN JETTA, 1.4 (A) Engine No: CAXB28457
Reg. Date: 18/09/2012 (Man. Year: 2012) Chassis No: WVVZZZ16ZDM001094
Colour: Black Odometer: 153657 km
Engine Capacity: 1390 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,182.00	1,787.00	5,395.00	75.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,080.00	1,420.00	56.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,682.00	2,867.00	6,815.00	70.39
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	9,682.00	2,300.00	7,382.00	76.24

INSPECTION

Date of Assignment: 03/02/2022
Date Inspected: 17/12/2021 Inspected At: CAR HUB HOLDINGS PTE LTD (HQ)
143 Bukit Timah Road
Singapore 229843
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Mar 2022)
Parts:	143	VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK6263T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,433.00 F	*- FL
2	1		*BOOTLID VOLKSWAGEN MOTIF	Essential	71.00 F	*71.00 FL
3	1		*BOOTLID JETTA EMBLEM	Essential	58.00 F	*58.00 FL
4	1		*BOOTLID TSI EMBLEM	Essential	31.00 F	*31.00 FL
5	1		*BOOTLID INNER LOCK	Not Necessary	158.00 F	*- FL
6	1		*BOOTLID STRIKER	Not Necessary	31.00 F	*- FL
7	1		*BOOTLID DRAUGHT WEATHERSTRIP	Not Necessary	168.00 F	*- FL
8	2		*TAILLAMP ASSEMBLY	Not Necessary	1,198.00 F	*- FL
9	1		*REAR END PANEL	Repair	990.00 F	*- FL
10	1		*REAR END PANEL INNER GARNISH	Not Necessary	125.00 F	*- FL
11	1		*REAR BUMPER	Dented/Chafed/Distorted	1,278.00 F	*1,056.00 FL
12	2		*REAR BUMPER REFLECTOR	Not Necessary	202.00 F	*- FL
13	1		*REAR BUMPER LOWER SKIRT	Cut/Chafed	396.00 F	*396.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Not Necessary	395.00 F	*- FL
15	2		*REAR BUMPER SIDE RETAINER	Cracked	118.00 F	*118.00 FL
16	2		*TEROSTAT	Not Necessary	160.00 FS	*- FS
17	1		*SET REAR BUMPER CLIP/FASTENER	Essential	50.00 FS	*30.00 FS
18	1		*SET REAR BUMPER REVERSE SENSOR	Malfunctioned due to impact	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,182.00	1,960.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	173.00
Total Parts (\$\$)	7,182.00	1,787.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT & CHECK FUNCTIONS INCLUDING TO REPLACE/RECALIBRATE REAR BUMPER REVERSE SENSORS TO SPECIFICATIONS	New	80.00	50.00
2	TO DISMANTLE/TRANSFER/REBUILD BOOTLID FITTINGS/ANCILLARY ACCESSORIES TO NEW BOOTLID	New	150.00	0.00
3	TO DISMANTLE/INSTALL REAR LUGGAGE FITTINGS/ANCILLARY ATTACHMENTS,BOARDS,TRIMS,GARNISHES,SPARE TYRE,TOOLS ETC.TO FACILITATE REPAIRS	New	150.00	30.00
4	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATIONS ETC	New	120.00	0.00
5	TO DISMANTLE/RENEW THE REAR ACCIDENT DAMAGED PORTIONS.TO HEAT,KNOCK-OUT,RESHAPE,STRAIGHTEN,ORIENTATE & ALIGN BOOTLID & ITS INNER REINFORCEMENT,BOOTLID INNER LOCK/STRIKER,REAR END PANEL,REAR FENDER O/S & N/S.REAR COMPARTMENT FLOOR/TYRE WELL PANEL ETC.TO SYMMETRICAL DIMENSIONS	New	1,000.00	400.00
6	TO PUTTY/PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOCUH-UP AFFECTED AREAS WITH POLYURETHANE PAINT }	New	1,000.00	600.00
7	TO DO RUST PROOFING AND CAVITIES PRESERVATION ON THE REPLACED AND REPAIRED PANELS }	New	0.00	0.00
Gross Labour Cost (\$\$)			2,500.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >