

Steve

REF: CS3/6RB21017730/Etf3-1

PRS

18 Sep 2012

Veh No: SLK 62631 Yr Regn: 1

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta c.c 1390

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 153657 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WRWZZZ16ZDM 00 1094

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

N/S	O/S

Tyre Size: F: 775/4-02R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm      L/Bal. 5 mm

D.O.A. 10/12/21 D.O.I. 17/12/21

Survey held at Car Hub

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction  
No GIA report

~~SUBMIT LUMP SUM \$2300, 4DAYS~~

RED: \$800: 25%

~~SUBMIT PPS REPORT~~

☐: Prell. Report

**Final Report**

Days Of Repair: 4

Resurvey No. of Trlp: \_\_\_\_\_

**Transportation:**

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

7: Interview (\$

: Tech. Invs (\$)

$$S + RS \rightleftharpoons SI$$

## Photos

Others

**Report Format :** \_\_\_\_\_